

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 11/07/2013 10:15 PM		4. Date/Time of Death 11/07/2013 11:09 PM		5. Fatal Case No 15			
6. Mine Information :											
a) Mining Company Name Vulcan Construction Materials, L.P.			b) Mine Name LITHIA SPRINGS QUARRY			c) Parent of Mining Company Vulcan Materials Company					
7. Mine Location : Lithia Springs			a) City		b) County Douglas		c) State GA		8. Mine ID Number: 09-00068	9. Union: NO	
10. Primary Mineral Mined: CRUSHED & BROKEN GRANITE MINI		11. Number of Mine Employees: 25		a) Total		b) Underground		c) Open Pit/Quarry 25		d) Mill/Prep Plant	e) Other
12. Contractor Name:						13. Union		14. Contractor ID Number:			
15. Contractor Address:			a) City		b) County		c) State		d) Zip Code		
16. Number of Contractor Employees:											
a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other			
17. Number of Persons in Mine at Time of Accident:						18. Number of Persons Unaccounted For:					
a) Mine Employees: 11		b) Contractor Employees: 0		a) Mine Employees: 0		b) Contractor Employees: 0					
19) Location of Accident									20. Mining Height:		
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)					Feet	Inches	
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility								
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1									
23. Victim Information :				a) Name Carl J. Clinton		b) Age 46					
c) Regular Job Title: Equipment Operator			d) Activity at Time of Accident: Operating Haul Truck			<input checked="" type="checkbox"/> Mine Employee					
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days			
a) Total:	27	b) at the mine:	4	c) at activity (23d)	3	4	6	d) with Contractor			
25. Autopsy Performed: If Yes, Location YES Douglas County, GA						26. Mine Telephone No.: (770) 948-6424					

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was operating a haul truck transporting material from the wash bins to a stock pile located northwest of two settling ponds. On the return trip to the wash bins, the haul truck veered off the left side of the haul road and traveled through a berm. The truck went over an embankment and overturned on its left side in a settling pond.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Caterpillar			29. Model: 769D		
30. District: M3000 Southeastern		32. Field Office: Macon GA			33. Event Number: 6584099
34. Accident Investigator: Randolph Billy		35. MSHA Person Notified: Michael Evans		Date 11/07/2013	Time 10:42 P
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Mike Harcher <i>MH</i>		Date 11/12/2013	
38. Reason For Amendment:					