

# Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Falling, Rdling or Sliding Rock /Materl		3. Date/Time of Accident 12/13/2013 10:50 AM		4. Date/Time of Death 12/13/2013 04:00 PM		5. Fatal Case No 21			
6. Mine Information :											
a) Mining Company Name Brown Brothers Sand Company			b) Mine Name Wittichen Stephen Plants			c) Parent of Mining Company Brown Brothers Sand Company					
7. Mine Location :		a) City Junction City		b) County Talbot		c) State GA		8. Mine ID Number: 09-00265		9. Union: NO	
10. Primary Mineral Mined: CONSTRUCTION SAND & GRAVEL M			11. Number of Mine Employees:		a) Total 7	b) Underground 0	c) Open Pit/Quarry 3		d) Mill/Prep Plant 3	e) Other 1	
12. Contractor Name:						13. Union		14. Contractor ID Number:			
15. Contractor Address:											
a) City		b) County			c) State			d) Zip Code			
16. Number of Contractor Employees:											
a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other			
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:						
a) Mine Employees: 3		b) Contractor Employees: 0			a) Mine Employees: 0		b) Contractor Employees: 0				
19) Location of Accident									20. Mining Height:		
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)					Feet	Inches	
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility								
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1									
23. Victim Information :											
a) Name Paul D. Barnes				b) Age 53							
c) Regular Job Title: Utility Worker				d) Activity at Time of Accident: Standing on bank in pit							
<input checked="" type="checkbox"/> Mine Employee											
24. Experience :											
Years		Weeks		Days		Years		Weeks		Days	
a) Total:		19		7		0		b) at the mine:		19 7 0	
						c) at activity (23d)				19 7 0	
						d) with Contractor				0 0 0	
25. Autopsy Performed: If Yes, Location YES Atlanta, Georgia								26. Mine Telephone No.: (706) 269-3257			

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was standing near the edge of a 27-foot bank when the bank collapsed engulfing him.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:				29. Model:					
30. District: M3000 Southeastern		32. Field Office: Macon GA				33. Event Number: 6644785			
34. Accident Investigator: Billy Rardolph				35. MSHA Person Notified: Judith Eterer		Date 12/13/2013		Time 11:18 A	
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Mike Harcher <i>MH</i>				Date 12/16/2013			
38. Reason For Amendment:									