

Preliminary Report of Accident



1. Accident Type: Fatal Injury	2. Accident Classification Machinery	3. Date/Time of Accident 06/04/2014 05:35 AM	4. Date/Time of Death 06/04/2014 05:35 AM	5. Fatal Case No 07
6. Mine Information :				
a) Mining Company Name Peabody Powder River Mining LLC		b) Mine Name North Antelope Rochelle Mine		c) Parent of Mining Company Peabody Energy
7. Mine Location : Wright	a) City Wright	b) County Campbell	c) State WY	8. Mine ID Number: 48-01353
9. Union: NO				
10. Primary Mineral Mined: BITUMINOUS	11. Number of Mine Employees: 1517	a) Total 1517	b) Underground 0	c) Open Pit/Quarry 850
d) Mill/Prep Plant 126	e) Other 541			
12. Contractor Name: Rogers Construction Inc.	13. Union NO		14. Contractor ID Number: S843	
15. Contractor Address: Whitewood	a) City Whitewood	b) County Pennington	c) State SD	d) Zip Code 57793
16. Number of Contractor Employees: 280	a) Total 280	b) Underground 0	c) Open Pit/Quarry 200	d) Mill/Prep Plant 80
e) Other 0				
17. Number of Persons in Mine at Time of Accident: a) Mine Employees: 270 b) Contractor Employees: 117		18. Number of Persons Unaccounted For: a) Mine Employees: 0 b) Contractor Employees: 0		
19) Location of Accident ☐ 01-Underground ☒ 03-Open Pit ☐ 07-Advance Mining ☐ 30-Mill/Prep Plant ☐ Other (specify) ☐ 02-Surface at Underground ☐ 06-Dredge Mining ☐ 08-Retreat Mining ☐ 99-Office Facility				20. Mining Height: Feet Inches 75 0
21. Nonfatal Injuries: 0	22. Fatal Injuries: 1			
23. Victim Information :				
a) Name Joshua L. Wishard		b) Age 25		
c) Regular Job Title: Equipment Operator				
d) Activity at Time of Accident: Removing large rock from crusher ☒ Contractor Employee				
24. Experience : a) Total: 24	Years Weeks Days 24	Years Weeks Days 15 3	Years Weeks Days 19	Years Weeks Days 24
25. Autopsy Performed: If Yes, Location YES Campbell County Coroners Office				26. Mine Telephone No.: (307) 464-4891

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

At approximately 05:35 am, on June 4, 2014, a 25 year old contract employee was fatally injured when he was crushed between the hood and the frame of a Metso Horizontal Impact Crusher. The crusher was located on the North Antelope Rochelle Mine at the Rail Loop East Scoria Crusher Pit. MSHA is investigating the accident.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Not listed	29. Model: M005615
30. District: C0900 Denver	32. Field Office: Gillette WY
33. Event Number: 4268353	
34. Accident Investigator: Lois J. Duwenhoegger	35. MSHA Person Notified: Peter Saint
Date 06/04/2014	
Time 05:53 AM	
36. Type of Report: Initial	37. Name of Preparer and Date Prepared: Lois Duwenhoegger
Date 06/05/2014	
38. Reason For Amendment:	