

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 07/23/2014 09:00 AM		4. Date/Time of Death 07/23/2014 11:30 AM		5. Fatal Case No 16						
6. Mine Information :														
a) Mining Company Name Cemex Construction Materials of Florida LL			b) Mine Name Brooksville South Cement Plant			c) Parent of Mining Company Cemex S A								
7. Mine Location :		a) City Brooksville		b) County Hernando		c) State FL		8. Mine ID Number: 08-01287		9. Union: NO				
10. Primary Mineral Mined: HYDRAULIC CEMENT			11. Number of Mine Employees:		a) Total 122		b) Underground 0		c) Open Pit/Quarry 0		d) Mill/Prep Plant 122		e) Other 0	
12. Contractor Name: New Line Transport/Tristate Carriers							13. Union NO		14. Contractor ID Number: B0350					
15. Contractor Address:		a) City Brooksville		b) County Hernando		c) State FL		d) Zip Code 34603						
16. Number of Contractor Employees:		a) Total 6		b) Underground 0		c) Open Pit/Quarry 0		d) Mill/Prep Plant 6		e) Other 0				
17. Number of Persons in Mine at Time of Accident:						18. Number of Persons Unaccounted For:								
a) Mine Employees: 84		b) Contractor Employees: 6		a) Mine Employees: 0		b) Contractor Employees: 0								
19) Location of Accident										20. Mining Height: Feet Inches				
<input type="checkbox"/> 01-Underground		<input type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input checked="" type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)						
<input type="checkbox"/> 02-Surface at Underground		<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility								
21. Nonfatal Injuries:			22. Fatal Injuries: 1											
23. Victim Information :		a) Name Ismael Santana			b) Age 51									
c) Regular Job Title: Commercial Truck Driver				d) Activity at Time of Accident: Hauling/Dumping Fly Ash				<input checked="" type="checkbox"/> Contractor Employee						
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days						
a) Total:		30 24 0		b) at the mine: 13 36 0		c) at activity (23d) 13 36 0		d) with Contractor 13 36 0						
25. Autopsy Performed: If Yes, Location YES Med Examiners Office, Leesburg, FL								26. Mine Telephone No.: (352) 799-7881						

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
The truck driver delivered a load of fly ash, parked, and exited his truck. A front-end loader backed down a ramp and struck the victim, pinning him against the truck.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Caterpillar				29. Model: 980H					
30. District: M3000 Southeastern		32. Field Office: Bartow FL				33. Event Number: 0917592			
34. Accident Investigator: Walter Deloach				35. MSHA Person Notified: Curtis Roth		Date 07/23/2014		Time 09:00 A	
36. Type of Report: Initial		37. Name of Preparer and Date Prepared Mike Hancher <i>MH</i>				Date 07/25/2014			
38. Reason For Amendment:									