

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Falling, Rolling or Sliding Rock /Materl		3. Date/Time of Accident 11/18/2014 12:10 PM		4. Date/Time of Death 11/18/2014 01:05 PM		5. Fatal Case No 21							
6. Mine Information :															
a) Mining Company Name Alcoa World Alumina LLC			b) Mine Name Bayer Alumina Plant			c) Parent of Mining Company Alcoa Inc									
7. Mine Location :		a) City Point Comfort		b) County Calhoun		c) State TX		8. Mine ID Number: 41-00320		9. Union: YES					
10. Primary Mineral Mined: ALUMINA MILLING			11. Number of Mine Employees:		a) Total 697	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant 457	e) Other 240						
12. Contractor Name: Turner Industries Group LLC						13. Union NO		14. Contractor ID Number: HPQ							
15. Contractor Address:		a) City Baton Rouge		b) County East Baton Rouge		c) State LA		d) Zip Code 70805							
16. Number of Contractor Employees:		a) Total 318		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant 318		e) Other					
17. Number of Persons in Mine at Time of Accident:						18. Number of Persons Unaccounted For:									
a) Mine Employees: 429		b) Contractor Employees: 318		a) Mine Employees: 0		b) Contractor Employees: 0									
19) Location of Accident									20. Mining Height:						
<input type="checkbox"/> 01-Underground	<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 04-Dredge Mining	<input type="checkbox"/> 05-Advance Mining	<input checked="" type="checkbox"/> 06-Mill/Prep Plant	<input type="checkbox"/> 07-Other (specify)	Feet	Inches							
<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 09-Office Facility	21. Nonfatal Injuries: 0	22. Fatal Injuries: 1												
23. Victim Information :															
a) Name Jerry McClelland			b) Age 42												
c) Regular Job Title: Job Site Supervisor					d) Activity at Time of Accident: Installing Tank Door					<input checked="" type="checkbox"/> Contractor Employee					
24. Experience :	Years		Weeks		Days		Years		Weeks		Days				
a) Total:	19	23	3	b) at the mine:	0	15	5	c) at activity (23d)	0	7	2	d) with Contractor	19	23	3
25. Autopsy Performed: NO								26. Mine Telephone No.: (361) 987-6948							

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
A crane was lifting a 2,500 pound door to be installed on a filtrate tank. The welded pad eye on the door broke loose and the door fell, pinning the victim on the concrete floor.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:				29. Model:			
30. District: M5000 South Central		32. Field Office: San Antonio TX				33. Event Number: 6652599	
34. Accident Investigator: Mark Williams			35. MSHA Person Notified: James T. Murph			Date 11/18/2014	Time 12:23 P
36. Type of Report: Amended		37. Name of Preparer and Date Prepared Mike Hancher <i>MH</i>				Date 11/20/2014	
38. Reason For Amendment: Items No. 12, 14							