

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 12/01/2014 10:30 AM		4. Date/Time of Death 12/01/2014 11:46 AM		5. Fatal Case No 23							
6. Mine Information :															
a) Mining Company Name MGQ Aggregates Incorporated			b) Mine Name Millersville Quarry			c) Parent of Mining Company Tim E Bell									
7. Mine Location :		a) City Helena		b) County Sandusky		c) State OH		8. Mine ID Number: 33-04511		9. Union: NO					
10. Primary Mineral Mined: CRUSHED & BROKEN LIMESTONE			11. Number of Mine Employees:		a) Total 8	b) Underground 0	c) Open Pit/Quarry 2	d) Mill/Prep Plant 5	e) Other 1						
12. Contractor Name: Mark's Excavating & Trucking						13. Union NO		14. Contractor ID Number: A4724							
15. Contractor Address:		a) City Norwalk		b) County Huron		c) State OH		d) Zip Code 44857-4857							
16. Number of Contractor Employees:		a) Total 11		b) Underground 0		c) Open Pit/Quarry 11		d) Mill/Prep Plant 0		e) Other 0					
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:										
a) Mine Employees: 5		b) Contractor Employees: 11			a) Mine Employees: 0		b) Contractor Employees: 0								
19) Location of Accident									20. Mining Height:						
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)					Feet	Inches					
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility												
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1													
23. Victim Information :															
a) Name Darwin O. Glover				b) Age 46											
c) Regular Job Title: Truck Driver				d) Activity at Time of Accident: Driving Haul Truck											
<input checked="" type="checkbox"/> Contractor Employee															
24. Experience :	Years Weeks Days			Years Weeks Days			Years Weeks Days			Years Weeks Days					
a) Total:	26	0	0	b) at the mine:	0	0	5	c) at activity (23d)	1	26	0	d) with Contractor	1	26	0
25. Autopsy Performed: If Yes, Location YES Toledo, OH								26. Mine Telephone No.: (419) 992-4235							

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was operating an empty, articulating haul truck on a roadway to get a load of material. The truck traveled over a berm and went into a large pond. Dive teams extricated the victim from the truck about 11:30 a.m.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Caterpillar			29. Model: 725		
30. District: M2000 Northeastern		32. Field Office: Hebron OH			33. Event Number: 6683762
34. Accident Investigator: Sean Murphy			35. MSHA Person Notified: Joseph M. Denk		Date 12/01/2014
					Time 11:42 A
36. Type of Report: Initial		37. Name of Preparer and Date Prepared Mike Hancher <i>MH</i>			Date 12/02/2014
38. Reason For Amendment:					