PR001 24-Oct-17

Preliminary Report of Accident

U.S. Department of Labor

Mine Safety and Health Administration

1000
//
//.\
1/-
((^/
\\\/
"//

1. Accident Type:	2. Accident Classification			3. Date/Time of Accident 4. Date/1		4. Date/Time of Dea	ıth	5. Fatal Case No
Fatal Injury	Powered Haulage			10/23/2017 04:27 AM		10/23/2017		14
6. Mine Information :		2						
a) Mining Company Name			c)	Parent of Mining C	ompany			
Marfork Coal Company		Horse Creek I	Eagle	Alpha Natural Resources, In				
7. Mine Location : a) City		b) Co	ounty	c) State 8. Mi		3. Mine ID Number:	Mine ID Number:	
Wh	itesville	Raleigh		WV		46-09091	46-09091	
10. Primary Mineral Mined:		11. Number of Mine	a) Total b)	Underground	c) Open Pit/6	5 (6)	ill/Prep Plant	e) Other
BITUMINOUS COAL UN	NDERGROUND	Employees:	122	117	· ·	0	0	5
12. Contractor Name:					13. Uni	on	14. Contrac	tor ID Number:
15. Contractor Address:	a) City		b)	County		c) State	d) Zi	p Code
16. Number of Contractor En	mployees:	a) Total b)	Underground	c) Open Pi	t/Quarry	d) Mill/Pro	ep Plant	e) Other
17. Number of Persons in Mi		dent:	_	18, Number of P	ersons Unacc			
a) Mine Employees:	30	b) Contractor Employe	es: 0	a) Mine Empl	oyees:	b) Co	ontractor Emp	20. Mining Height:
X 01-Underground 03-Open Pit 07-Advance Mining 30-Mill/Prep Plant 02-Surface at Underground 06-Dredge Mining 08-Retreat Mining 99-Office Facility							3-1//	Feet Inches 5 0
The state of the s	COLORES Land	ital Injuries:	T OG-Ketreat	vining		,		
21. Nonfatal Injuries:	0	1						
23. Victim Information:	Jame	a) Name s R. Adkins		b) Age 48				
c) Regular Job Title: Belt Examiner		d) Activit	y at Time of Acci	dent: Belt Examine	r		X M	line Employee
24. Experience : Years Weeks Days Years Weeks Days					Years Week	s Days		Years Weeks Days
a) Total: 18	10 ь) at the mine: 1 34	t c) at	activity (23d)	4 30	1 d) with	Contractor	
25. Autopsy Performed:	If Yes, Locatio	n				26. Mine Telepho	ne No.:	
NO		III TO VOICE AND				(304) 854-1837	
27. Description of Accident (include equipment	involved, the exact loca	tion in the mine, a	and status of rescue	and recovery	operations):		
The victim was examinin transfer point. The victin Marfork Processing. The	n was conveyed	through the belt tra	belts. It appears nsfer system f	ars he fell onto the from the Horse C	ne No. 1 co Creek Eagle	nveyor belt at the mine to the raw	e No. 2 to N coal stock	lo.1 conveyor belt pile located at
	=							
The information provided in regarding the cause of the ac		d on preliminary data O	NLY and does no	t represent final de	terminations	regarding the natur	e of the incide	ent or conclusions
28. Equipment Manufacture	r: Not R	eported		2	29, Model:			
30. District: 32. Field Office CO400 Mt. Hope				Mt. Hope WV		33. Eve	33, Event Number: 6302	
				son Notified:		L	ite	Time
Larry B. Hedrick			150 AND 150 AN			10/23/		
				Phillips		101201	2011	07:32 A
36. Type of Report:	nitial	37. Name of Preparer	L			10/20/	Date 10/24/20	