

# Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Fall of Face, Rib, Pillar or Highwall		3. Date/Time of Accident 02/06/2018 03:45 AM		4. Date/Time of Death 02/06/2018 03:45 AM		5. Fatal Case No 01		
6. Mine Information :										
a) Mining Company Name Wolf Run Mining LLC			b) Mine Name Sentinel Mine			c) Parent of Mining Company Arch Coal Inc				
7. Mine Location :		a) City Phillippi		b) County Barbour		c) State WV		8. Mine ID Number: 46-04168		9. Union: NO
10. Primary Mineral Mined: BITUMINOUS COAL UNDERGROUND		11. Number of Mine Employees:		a) Total 325	b) Underground 271	c) Open Pit/Quarry		d) Mill/Prep Plant 24	e) Other 30	
12. Contractor Name:						13. Union NO		14. Contractor ID Number:		
15. Contractor Address:										
a) City		b) County			c) State			d) Zip Code		
16. Number of Contractor Employees:										
a) Total 6		b) Underground 6		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other 0		
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 77		b) Contractor Employees: 6			a) Mine Employees: 0		b) Contractor Employees: 0			
19) Location of Accident								20. Mining Height:		
<input checked="" type="checkbox"/> 01-Underground	<input type="checkbox"/> 03-Open Pit		<input checked="" type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		Feet 6	Inches 8
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility					
21. Nonfatal Injuries:		22. Fatal Injuries: 1								
23. Victim Information :										
a) Name Leonard Griffith				b) Age 52						
c) Regular Job Title: Electrician				d) Activity at Time of Accident: Servicing continuous-mining machine				<input checked="" type="checkbox"/> Mine Employee		
24. Experience :										
Years	Weeks		Days		Years	Weeks		Days		
a) Total: 13	b) at the mine: 3		3		1		c) at activity (23d) 3		3	
1		d) with Contractor								
25. Autopsy Performed: If Yes, Location NO						26. Mine Telephone No.: (304) 457-1895				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

On Tuesday, February 6, 2018, at approximately 3:45 a.m., a miner, working as a mechanic was found between a coal rib and the continuous-mining machine. Part of a rib roll measuring 36 to 42-inches long, 28 inches high, and up to 14 inches, thick was found on top of the victim. The victim was transported to the Broaddus Hospital where he was pronounced dead.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:				29. Model:			
30. District: C0300 Morgantown		32. Field Office: Bridgeport WV				33. Event Number: 6278587	
34. Accident Investigator: Michael Fasouletos			35. MSHA Person Notified: Steven Stankus			Date 02/06/2018	Time 04:14 A
36. Type of Report: Amended		37. Name of Preparer and Date Prepared AEW for Carlos Mosley				Date 02/07/2018	

38. Reason For Amendment:

Additional information obtained from the tracking system indicates the miner was first discovered at approximately 3:45 A.M.