

# Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Fall of Face, Rib, Pillar or Highwall		3. Date/Time of Accident 12/11/2018 01:55 PM		4. Date/Time of Death 12/11/2018 05:45 PM		5. Fatal Case No 9				
6. Mine Information :												
a) Mining Company Name Cedar Lake Mining, Inc.			b) Mine Name Little Spring Creek Mine			c) Parent of Mining Company Freddy Hunt; Michael T Costello						
7. Mine Location :		a) City Jasper		b) County Walker		c) State AL		8. Mine ID Number: 01-03444		9. Union: NO		
10. Primary Mineral Mined: BITUMINOUS			11. Number of Mine Employees:		a) Total 40	b) Underground 0	c) Open Pit/Quarry 40		d) Mill/Prep Plant 0	e) Other 0		
12. Contractor Name:						13. Union		14. Contractor ID Number:				
15. Contractor Address:		a) City		b) County		c) State		d) Zip Code				
16. Number of Contractor Employees:		a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other		
17. Number of Persons in Mine at Time of Accident:						18. Number of Persons Unaccounted For:						
a) Mine Employees: 27		b) Contractor Employees: 0		a) Mine Employees: 0		b) Contractor Employees: 0						
19) Location of Accident									20. Mining Height:			
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)					Feet	Inches		
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility						1	6		
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1										
23. Victim Information :												
a) Name Micky E. Cook					b) Age 38							
c) Regular Job Title: Front End Loader Operator												
d) Activity at Time of Accident: Front End Loader Operator <input checked="" type="checkbox"/> Mine Employee												
24. Experience :												
Years Weeks Days			Years Weeks Days			Years Weeks Days			Years Weeks Days			
a) Total:	14	0	0	b) at the mine:	1	21	0	c) at activity (23d)	14	0	0	d) with Contractor
25. Autopsy Performed: If Yes, Location						26. Mine Telephone No.:						

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):  
The victim was operating a front end loader to push rock so that it could be loaded out of the pit. A portion of the highwall collapsed and crushed the operator's cab of the front end loader where the victim was located. A first responder who was a medic assessed the victim but no pulse was detected.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Caterpillar				29. Model: 972G			
30. District: C0700 Barbourville		32. Field Office: Birmingham AL			33. Event Number: 4456676		
34. Accident Investigator: Jarvis F. Westery				35. MSHA Person Notified: Craig Plumley		Date 12/11/2018	Time 03:26 PM
36. Type of Report: Amended		37. Name of Preparer and Date Prepared: Jarvis Westery				Date 12/11/2018	
38. Reason For Amendment: Correct spelling of victim's first name; Correct victim's experience							