

Preliminary Report of Accident



| | | | | | | | | | | | |
|---|---|---|---|---|---|--|--|-----------------------------------|--------------------|-----------------|--------|
| 1. Accident Type: Fatal Injury | | 2. Accident Classification Powered Haulage | | 3. Date/Time of Accident 01/14/2019 11:10 AM | | 4. Date/Time of Death 01/14/2019 11:10 AM | | 5. Fatal Case No 2 | | | |
| 6. Mine Information : | | | | | | | | | | | |
| a) Mining Company Name Tennco Inc. | | | b) Mine Name Toms Fork Mine | | | c) Parent of Mining Company | | | | | |
| 7. Mine Location : | | a) City Balkan | | b) County Bell | | c) State KY | | 8. Mine ID Number: 15-19844 | | 9. Union: NO | |
| 10. Primary Mineral Mined: BITUMINOUS COAL UNDERGROUND | | 11. Number of Mine Employees: | | a) Total 26 | b) Underground 21 | c) Open Pit/Quarry 0 | | d) Mill/Prep Plant 0 | e) Other 5 | | |
| 12. Contractor Name: Irtec | | | | | | 13. Union NO | | 14. Contractor ID Number: Z142 | | | |
| 15. Contractor Address: | | a) City Caryville | | b) County Campbell | | c) State TN | | d) Zip Code 37714-7714 | | | |
| 16. Number of Contractor Employees: | | a) Total 2 | b) Underground 2 | | c) Open Pit/Quarry 0 | | d) Mill/Prep Plant 0 | e) Other 0 | | | |
| 17. Number of Persons in Mine at Time of Accident: | | | | | 18. Number of Persons Unaccounted For: | | | | | | |
| a) Mine Employees: 10 | | b) Contractor Employees: 2 | | | a) Mine Employees: 0 | | b) Contractor Employees: 0 | | | | |
| 19) Location of Accident | | | | | | | | | 20. Mining Height: | | |
| <input checked="" type="checkbox"/> 01-Underground | <input type="checkbox"/> 03-Open Pit | | <input checked="" type="checkbox"/> 07-Advance Mining | | <input type="checkbox"/> 30-Mill/Prep Plant | | <input type="checkbox"/> Other (specify) | | Feet 4 | Inches 6 | |
| <input type="checkbox"/> 02-Surface at Underground | <input type="checkbox"/> 06-Dredge Mining | | <input type="checkbox"/> 08-Retreat Mining | | <input type="checkbox"/> 99-Office Facility | | | | | | |
| 21. Nonfatal Injuries: 0 | | 22. Fatal Injuries: 1 | | | | | | | | | |
| 23. Victim Information : | | | | | | | | | | | |
| a) Name Jeffery N. Slone | | | | | b) Age 56 | | | | | | |
| c) Regular Job Title: Spad man | | | | | | | | | | | |
| d) Activity at Time of Accident: Taking mining height measurements <input checked="" type="checkbox"/> Contractor Employee | | | | | | | | | | | |
| 24. Experience : | | | | | | | | | | | |
| Years Weeks Days | | | Years Weeks Days | | | Years Weeks Days | | | Years Weeks Days | | |
| a) Total: | 30 0 0 | | b) at the mine: | | 0 12 0 | c) at activity (23d) | | 30 0 0 | d) with Contractor | | 15 0 0 |
| 25. Autopsy Performed: If Yes, Location YES Frankfort, Kentucky | | | | | | 26. Mine Telephone No.: (865) 851-6800 | | | | | |

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

A two-person spad crew was on the 001-0 MMU. While one spad crew member was setting up the transit in the No. 4 entry, the victim, who was the other spad crew member, was in the No. 3 entry taking measurements of the mining height. A shuttle car traveling in the No. 3 entry toward the feeder struck and fatally injured him.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

| | | | | | | | | | |
|---|--|--|--|---|------------------------------|--------------------|--|------------------|--|
| 28. Equipment Manufacturer: Joy Machinery Co. (Joy Manufacturing Co) | | | | 29. Model: 10 SC | | | | | |
| 30. District: C0700 Barbourville | | 32. Field Office: Birmingham AL | | | 33. Event Number: 4457399 | | | | |
| 34. Accident Investigator: Ricky L. Suffridge | | | | 35. MSHA Person Notified: Samuel R. Creasy | | Date 01/14/2019 | | Time 11:20 AM | |
| 36. Type of Report: Amended | | 37. Name of Preparer and Date Prepared: Ricky L Suffridge | | | | Date 02/12/2019 | | | |
| 38. Reason For Amendment: Correct Model No. of Equipment | | | | | | | | | |