

Preliminary Report of Accident
PR001 06/27/2019

U.S. Department of Labor
Mine Safety and Health Administration



1. Accident Type F - Fatal Injury		2. Accident Classification 12 - Powered Haulage		3. Date/Time of Accident 06/24/2019 3:20 PM		4. Date/Time of Death 06/24/2019 3:20 PM		5. Fatal Case No 11					
6. Mine Information													
a) Mining Company Name:		Dolese Bros. Co.											
b) Mine Name:		East Sand Plant											
c) Parent of Mining Company:		Dolese Brothers Company											
7. Mine Location Information						8. Mine ID Number		9. Union					
a) City Oklahoma City		b) County Oklahoma		c) State OK		34-02056		No					
10. Primary Mineral Mined				11. Number of Employees									
				a) Total 9		b) Underground		c) Open Pit/Quarry 5		d) Mill/Prep Plant 4		e) Other	
12. Contractor Name Northwest Crane Service, LLC						13. Contractor Union		14. Contractor ID Number D581					
15. Contractor Address													
a) City Woodward		b) County			c) State OK		d) Zip Code 73801						
16. Number of Contractor Employees													
a) Total 10		b) Underground			c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other 10				
17. Number of Persons in Mine at Time of Accident				18. Number of Persons Unaccounted for									
a) Mine Employees 9		b) Contractor Employees 4		a) Mine Employees		b) Contractor Employees							
19. Accident Location 06 - Dredge Mining								20. Mining Height					
								Feet		Inches			
21. Nonfatal Injuries		22. Fatal Injuries 1											
23. Victims Information													
Neil P Witte													
a) First Name Neil		a) MI P	a) Last Name Witte		b) Age 34	c) Regular Job Title Crane Operator		d) Activity at Time of Accident Moving mobile equipment off site		Employee Contractor Employee			
24. Mining Experience													
a) Total Experience 10 Years 0 Weeks 0 Days		b) Experience at the Mine 0 Years 0 Weeks 0 Days			c) Experience at the Activity at the Time of the Accident 10 Years 43 Weeks 5 Days			d) Experience with Contractor 10 Years 0 Weeks 0 Days					
25. Autopsy Performed No		If Yes, Location											
26. Mine Telephone No. (405) 620-6950													
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) A contract miner was fatally injured when he fell beneath the wheels of a tractor-trailer. The miners were using a bulldozer to pull the tractor-trailer, which had become stuck in the sand. The victim was standing approximately 20-30 feet away, and as the tractor-trailer began to move, he was seen walking toward the side of the truck. The victim died at the scene from crushing injuries. <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>													
28. Equipment Manufacturer Kenworth					29. Model T880								
30. District M5000 - South Central District - Dallas					32. Field Office M5861 - Norman OK Field Office			33. Event Number 6734489					
34. Accident Investigator													
First Name Laurence		MI M	Last Name Dunlap										
35. MSHA Person Notified													
First Name Brett		MI	Last Name Barrick			Date/Time Notified 06/24/2019 3:37 PM							
36. Type of Report Initial		37. Name of Preparer			Date Prepared								
		Full Name Elwood Burriss			06/26/2019								
38. Reason for Amendment													