

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



PR001 08/20/2020

1. Accident Type F - Fatal Injury		2. Accident Classification 05 - Falling, Rolling or Sliding Rock /Material		3. Date/Time of Accident 08/18/2020 6:30 AM		4. Date/Time of Death 08/19/2020 12:43 PM		5. Fatal Case No FAI-6871921-1		
6. Mine Information										
a) Mining Company Name:		Hi-Grade Materials Co.								
b) Mine Name:		HJ Hove								
c) Parent of Mining Company:		Robar Enterprises Inc								
7. Mine Location Information						8. Mine ID Number		9. Union		
a) City Hesperia		b) County Riverside		c) State CA		04-01854		No		
10. Primary Mineral Mined Construction Sand & Gravel Mining, N.E.C.				11. Number of Employees			d) Mill/Prep Plant		e) Other	
				a) Total 20	b) Underground	c) Open Pit/Quarry 18			2	
12. Contractor Name						13. Contractor Union		14. Contractor ID Number		
15. Contractor Address										
a) City		b) County			c) State			d) Zip Code		
16. Number of Contractor Employees										
a) Total		b) Underground			c) Open Pit/Quarry			d) Mill/Prep Plant		e) Other
17. Number of Persons in Mine at Time of Accident				18. Number of Persons Unaccounted for						
a) Mine Employees 12		b) Contractor Employees		a) Mine Employees 0		b) Contractor Employees				
19. Accident Location 03 - Open Pit								20. Mining Height		
								Feet	Inches	
21. Nonfatal Injuries		22. Fatal Injuries 1								
23. Victims Information										
Diego Resendiz										
a) First Name	a) MI	a) Last Name		b) Age	c) Regular Job Title		d) Activity at Time of Accident		Employee	
Diego		Resendiz		21	Laborer		Unplugging Crusher		Mine Employee	
24. Mining Experience										
a) Total Experience		b) Experience at the Mine			c) Experience at the Activity at the Time of the Accident			d) Experience with Contractor		
1 Years 12 Weeks 6 Days		1 Years 12 Weeks 6 Days			1 Years 12 Weeks 6 Days			0 Years 0 Weeks 0 Days		
25. Autopsy Performed		If Yes, Location								
26. Mine Telephone No. (760) 775-7500										
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)										
The victim entered the cone crusher to remove a blockage of material in the chute. While he was inside the cone crusher, material flowed from the chute engulfing his legs and lower torso. He was extricated by the fire department and flown to the hospital where he died the next day.										
<i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>										
28. Equipment Manufacturer Not listed Telsmith					29. Model 66S					
30. District M7000 - Vacaville District					32. Field Office M7831 - San Bernardino CA Field Office			33. Event Number 6871921		
34. Accident Investigator										
First Name		MI	Last Name							
Charles			Snare							
35. MSHA Person Notified										
First Name		MI	Last Name		Date/Time Notified					
Gary			Hebel		08/18/2020 7:37 AM					
36. Type of Report Initial		37. Name of Preparer Full Name			Date Prepared					
		James Fitch			08/18/2020					
38. Reason for Amendment										