

# Preliminary Report of Accident

U.S. Department of Labor  
Mine Safety and Health Administration



PR001 08/20/2020

<b>1. Accident Type</b> F - Fatal Injury		<b>2. Accident Classification</b> 05 - Machinery		<b>3. Date/Time of Accident</b> 08/18/2020 6:30 AM		<b>4. Date/Time of Death</b> 08/19/2020 12:43 PM		<b>5. Fatal Case No</b> FAI-6871921-1		
<b>6. Mine Information</b>										
a) Mining Company Name:		Hi-Grade Materials Co.								
b) Mine Name:		HJ Hove								
c) Parent of Mining Company:		Robar Enterprises Inc								
<b>7. Mine Location Information</b>						<b>8. Mine ID Number</b>		<b>9. Union</b>		
a) City Hesperia		b) County Riverside		c) State CA		04-01854		No		
<b>10. Primary Mineral Mined</b> Construction Sand & Gravel Mining, N.E.C.				<b>11. Number of Employees</b>						
				a) Total 20		b) Underground 18		c) Open Pit/Quarry 2		
<b>12. Contractor Name</b>						<b>13. Contractor Union</b>		<b>14. Contractor ID Number</b>		
<b>15. Contractor Address</b>										
a) City		b) County			c) State			d) Zip Code		
<b>16. Number of Contractor Employees</b>										
a) Total		b) Underground			c) Open Pit/Quarry			d) Mill/Prep Plant		e) Other
<b>17. Number of Persons in Mine at Time of Accident</b>				<b>18. Number of Persons Unaccounted for</b>						
a) Mine Employees 12		b) Contractor Employees		a) Mine Employees 0		b) Contractor Employees				
<b>19. Accident Location</b> 03 - Open Pit								<b>20. Mining Height</b>		
								Feet    Inches		
<b>21. Nonfatal Injuries</b>		<b>22. Fatal Injuries</b> 1								
<b>23. Victims Information</b>										
Diego Resendiz										
a) First Name Diego		a) MI	a) Last Name Resendiz		b) Age 21	c) Regular Job Title Laborer		d) Activity at Time of Accident Unplugging Crusher		Employee Mine Employee
<b>24. Mining Experience</b>										
a) Total Experience 1 Years 12 Weeks 6 Days		b) Experience at the Mine 1 Years 12 Weeks 6 Days			c) Experience at the Activity at the Time of the Accident 1 Years 12 Weeks 6 Days			d) Experience with Contractor 0 Years 0 Weeks 0 Days		
<b>25. Autopsy Performed</b>		If Yes, Location								
<b>26. Mine Telephone No.</b> (760) 775-7500										
<b>27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)</b>										
The victim entered the cone crusher to remove a blockage of material in the chute. While he was inside the cone crusher, material flowed from the chute engulfing his legs and lower torso. He was extricated by the fire department and flown to the hospital where he died the next day.										
<i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>										
<b>28. Equipment Manufacturer</b> Not listed    Telsmith				<b>29. Model</b> 66S						
<b>30. District</b> M7000 - Vacaville District				<b>32. Field Office</b> M7831 - San Bernardino CA Field Office				<b>33. Event Number</b> 6871921		
<b>34. Accident Investigator</b>										
First Name Charles		MI	Last Name Snare							
<b>35. MSHA Person Notified</b>										
First Name Gary		MI	Last Name Hebel			Date/Time Notified 08/18/2020 7:37 AM				
<b>36. Type of Report</b> Initial		<b>37. Name of Preparer</b> Full Name James Fitch			Date Prepared 08/18/2020					
<b>38. Reason for Amendment</b>										