

# Preliminary Report of Accident

U.S. Department of Labor  
Mine Safety and Health Administration



PR001 05/03/2021

<b>1. Accident Type</b> F - Fatal Injury		<b>2. Accident Classification</b> 12 - Powered Haulage		<b>3. Date/Time of Accident</b> 04/22/2021 4:15 PM		<b>4. Date/Time of Death</b> 04/22/2021 4:15 PM		<b>5. Fatal Case No</b> FAI-6487939-1		
<b>6. Mine Information</b>										
<b>a) Mining Company Name:</b>		Broadfoot Sand & Gravel Inc								
<b>b) Mine Name:</b>		BROADFOOT PIT #2								
<b>c) Parent of Mining Company:</b>		Austin Broadfoot et al								
<b>7. Mine Location Information</b>					<b>8. Mine ID Number</b>		<b>9. Union</b>			
<b>a) City</b> KEARNEY		<b>b) County</b> Buffalo		<b>c) State</b> NE		25-01118		No		
<b>10. Primary Mineral Mined</b> Construction Sand & Gravel Mining, N.E.C.				<b>11. Number of Employees</b>			<b>d) Mill/Prep Plant</b>		<b>e) Other</b>	
				<b>a) Total</b> 3	<b>b) Underground</b>		<b>c) Open Pit/Quarry</b> 1	1	1	
<b>12. Contractor Name</b>						<b>13. Contractor Union</b>		<b>14. Contractor ID Number</b>		
<b>15. Contractor Address</b>										
<b>a) City</b>		<b>b) County</b>			<b>c) State</b>			<b>d) Zip Code</b>		
<b>16. Number of Contractor Employees</b>										
<b>a) Total</b>		<b>b) Underground</b>			<b>c) Open Pit/Quarry</b>			<b>d) Mill/Prep Plant</b>		<b>e) Other</b>
<b>17. Number of Persons in Mine at Time of Accident</b>				<b>18. Number of Persons Unaccounted for</b>						
<b>a) Mine Employees</b> 3		<b>b) Contractor Employees</b>		<b>a) Mine Employees</b> 0		<b>b) Contractor Employees</b>				
<b>19. Accident Location</b> 06 - Dredge Mining								<b>20. Mining Height</b> 55 Feet    Inches		
<b>21. Nonfatal Injuries</b>		<b>22. Fatal Injuries</b> 1								
<b>23. Victims Information</b>										
<b>Robert E Beam</b>										
<b>a) First Name</b> Robert	<b>a) MI</b> E	<b>a) Last Name</b> Beam		<b>b) Age</b> 53	<b>c) Regular Job Title</b> Dredge Operator			<b>d) Activity at Time of Accident</b> Operating his personal truck		<b>Employee</b> Mine Employee
<b>24. Mining Experience</b>										
<b>a) Total Experience</b> 6 Years 40 Weeks 0 Days		<b>b) Experience at the Mine</b> 2 Years 36 Weeks 0 Days			<b>c) Experience at the Activity at the Time of the Accident</b> 2 Years 36 Weeks 0 Days			<b>d) Experience with Contractor</b> 0 Years 0 Weeks 0 Days		
<b>25. Autopsy Performed</b> Yes		<b>If Yes, Location</b>								
<b>26. Mine Telephone No.</b> (308) 236-5301										
<b>27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)</b> A miner was exiting the mine property in his personal vehicle. The gate was partially closed and entered the vehicle striking the victim.  <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>										
<b>28. Equipment Manufacturer</b> Not listed    General Motors Corporation (GMC)					<b>29. Model</b> 1997 GMC K1500 4X4					
<b>30. District</b> C1000 - Madisonville District				<b>32. Field Office</b> C1005 - Topeka KS Field Office			<b>33. Event Number</b> 6487939			
<b>34. Accident Investigator</b>										
<b>First Name</b>		<b>MI</b>		<b>Last Name</b>						
<b>35. MSHA Person Notified</b>										
<b>First Name</b> Curtis		<b>MI</b> R		<b>Last Name</b> Hardison			<b>Date/Time Notified</b> 04/22/2021 4:47 PM			
<b>36. Type of Report</b> Amended		<b>37. Name of Preparer</b>			<b>Date Prepared</b>					
		<b>Full Name</b> Curtis R Hardison			04/23/2021					
<b>38. Reason for Amendment</b> Received new information on miner's total work experience. Report is correct now.										