

# Preliminary Report of Accident

U.S. Department of Labor  
Mine Safety and Health Administration



PR001 08/05/2021

<b>1. Accident Type</b> F - Fatal Injury	<b>2. Accident Classification</b> 12 - Powered Haulage	<b>3. Date/Time of Accident</b> 08/03/2021 5:00 AM	<b>4. Date/Time of Death</b> 08/03/2021 6:16 AM	<b>5. Fatal Case No</b> FAI-6889110-1
<b>6. Mine Information</b>				
<b>a) Mining Company Name:</b> TXI Operations LP		<b>b) Mine Name:</b> Bridgeport Stone Plant		
<b>c) Parent of Mining Company:</b> Martin Marietta Materials Inc				
<b>7. Mine Location Information</b>			<b>8. Mine ID Number</b> 41-00007	<b>9. Union</b> No
<b>a) City</b> BRIDGEPORT		<b>b) County</b> Wise	<b>c) State</b> TX	
<b>10. Primary Mineral Mined</b> Crushed & Broken Limestone Mining, N.E.C.		<b>11. Number of Employees</b>		
		<b>a) Total</b> 83	<b>b) Underground</b>	<b>c) Open Pit/Quarry</b> 43
			<b>d) Mill/Prep Plant</b> 35	<b>e) Other</b> 5
<b>12. Contractor Name</b>			<b>13. Contractor Union</b>	<b>14. Contractor ID Number</b>
<b>15. Contractor Address</b>				
<b>a) City</b>		<b>b) County</b>	<b>c) State</b>	<b>d) Zip Code</b>
<b>16. Number of Contractor Employees</b>				
<b>a) Total</b>		<b>b) Underground</b>	<b>c) Open Pit/Quarry</b>	<b>d) Mill/Prep Plant</b>
			<b>e) Other</b>	
<b>17. Number of Persons in Mine at Time of Accident</b>			<b>18. Number of Persons Unaccounted for</b>	
<b>a) Mine Employees</b> 47		<b>b) Contractor Employees</b>		
		<b>a) Mine Employees</b>		<b>b) Contractor Employees</b>
<b>19. Accident Location</b> 03 - Open Pit				<b>20. Mining Height</b> 60 Feet 0 Inches
<b>21. Nonfatal Injuries</b> 0	<b>22. Fatal Injuries</b> 1			
<b>23. Victims Information</b>				
<b>Reyes Lovington JR</b>				
<b>a) First Name</b> Reyes	<b>a) MI</b>	<b>a) Last Name</b> Lovington JR	<b>b) Age</b> 62	<b>c) Regular Job Title</b> Utility
<b>d) Activity at Time of Accident</b> Walking to work area				<b>Employee</b> Mine Employee
<b>24. Mining Experience</b>				
<b>a) Total Experience</b> 14 Years 48 Weeks 4 Days		<b>b) Experience at the Mine</b> 12 Years 48 Weeks 4 Days		<b>c) Experience at the Activity at the Time of the Accident</b> 12 Years 48 Weeks 4 Days
				<b>d) Experience with Contractor</b> 0 Years 0 Weeks 0 Days
<b>25. Autopsy Performed</b> No		<b>If Yes, Location</b>		
<b>26. Mine Telephone No.</b> (972) 647-7200				
<b>27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)</b> A miner was run over by a haul truck while he was walking to his normal work area.  <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>				
<b>28. Equipment Manufacturer</b> Peterbilt			<b>29. Model</b> 2006	
<b>30. District</b> M5000 - Dallas District			<b>32. Field Office</b> M5671 - Dallas TX Field Office	
<b>33. Event Number</b> 6889110				
<b>34. Accident Investigator</b>				
<b>First Name</b> Ty		<b>MI</b>	<b>Last Name</b> Fisher	
<b>35. MSHA Person Notified</b>				
<b>First Name</b> Homer		<b>MI</b> A	<b>Last Name</b> Pricer	<b>Date/Time Notified</b> 08/03/2021 5:36 AM
<b>36. Type of Report</b> Initial		<b>37. Name of Preparer</b> <b>Full Name</b> Ty Fisher		<b>Date Prepared</b> 08/03/2021
<b>38. Reason for Amendment</b>				