

# Preliminary Report of Accident

U.S. Department of Labor  
Mine Safety and Health Administration



PR001 12/20/2021

<b>1. Accident Type</b> F - Fatal Injury		<b>2. Accident Classification</b> 12 - Powered Haulage		<b>3. Date/Time of Accident</b> 12/13/2021 10:42 AM		<b>4. Date/Time of Death</b> 12/13/2021 10:49 AM		<b>5. Fatal Case No</b> FAI-6889369-1		
<b>6. Mine Information</b>										
<b>a) Mining Company Name:</b>		Martin Marietta Materials Southwest, Inc.								
<b>b) Mine Name:</b>		Liberty Ranch								
<b>c) Parent of Mining Company:</b>		Norvarem S A U								
<b>7. Mine Location Information</b>						<b>8. Mine ID Number</b>		<b>9. Union</b>		
<b>a) City</b> THE WOODLANDS		<b>b) County</b> Liberty		<b>c) State</b> TX		41-05268		No		
<b>10. Primary Mineral Mined</b> Common Sand Mining				<b>11. Number of Employees</b>			<b>d) Mill/Prep Plant</b>		<b>e) Other</b>	
				<b>a) Total</b> 12	<b>b) Underground</b>		<b>c) Open Pit/Quarry</b> 11		1	
<b>12. Contractor Name</b>						<b>13. Contractor Union</b>		<b>14. Contractor ID Number</b>		
<b>15. Contractor Address</b>										
<b>a) City</b>		<b>b) County</b>			<b>c) State</b>			<b>d) Zip Code</b>		
<b>16. Number of Contractor Employees</b>										
<b>a) Total</b>		<b>b) Underground</b>			<b>c) Open Pit/Quarry</b>			<b>d) Mill/Prep Plant</b>		<b>e) Other</b>
<b>17. Number of Persons in Mine at Time of Accident</b>					<b>18. Number of Persons Unaccounted for</b>					
<b>a) Mine Employees</b> 12		<b>b) Contractor Employees</b>			<b>a) Mine Employees</b>		<b>b) Contractor Employees</b>			
<b>19. Accident Location</b> 00 - Other Tarping area								<b>20. Mining Height</b>		
								Feet	Inches	
<b>21. Nonfatal Injuries</b>		<b>22. Fatal Injuries</b> 1								
<b>23. Victims Information</b>										
<b>Eduardo Jimenez- Gonzales</b>										
<b>a) First Name</b> Eduardo	<b>a) MI</b>	<b>a) Last Name</b> Jimenez- Gonzales		<b>b) Age</b> 24	<b>c) Regular Job Title</b> Truck Driver		<b>d) Activity at Time of Accident</b> Assisting another truck driver		<b>Employee</b> Other Employee	
<b>24. Mining Experience</b>										
<b>a) Total Experience</b> 0 Years 32 Weeks 0 Days		<b>b) Experience at the Mine</b> 0 Years 32 Weeks 0 Days			<b>c) Experience at the Activity at the Time of the Accident</b> 0 Years 0 Weeks 0 Days			<b>d) Experience with Contractor</b> 0 Years 0 Weeks 0 Days		
<b>25. Autopsy Performed</b> No		<b>If Yes, Location</b>								
<b>26. Mine Telephone No.</b> (346) 305-0656										
<b>27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)</b> A customer truck driver stopped at a designated tarping area and was assisting another driver with a rear trailer indicator light. The victim's truck moved forward and pinned him against the back of the other driver's truck.  <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>										
<b>28. Equipment Manufacturer</b> Peterbilt				<b>29. Model</b> 359M19						
<b>30. District</b> M5000 - Dallas District				<b>32. Field Office</b> M5651 - Broussard LA Field Office				<b>33. Event Number</b> 6889369		
<b>34. Accident Investigator</b>										
<b>First Name</b> Thomas		<b>MI</b> J	<b>Last Name</b> Balch							
<b>35. MSHA Person Notified</b>										
<b>First Name</b> Brett		<b>MI</b>	<b>Last Name</b> Barrick			<b>Date/Time Notified</b> 12/13/2021 10:45 AM				
<b>36. Type of Report</b> Initial		<b>37. Name of Preparer</b>			<b>Date Prepared</b>					
		<b>Full Name</b> Thomas J Balch			12/13/2021					
<b>38. Reason for Amendment</b>										