

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



PR001 01/20/2021

1. Accident Type F - Fatal Injury		2. Accident Classification 12 - Powered Haulage		3. Date/Time of Accident 01/19/2021 1:00 PM		4. Date/Time of Death 01/19/2021 1:00 PM		5. Fatal Case No FAI-6781141-01	
6. Mine Information									
a) Mining Company Name:		Geneva Rock Products Inc							
b) Mine Name:		HANSEN PIT							
c) Parent of Mining Company:		CCI (Clyde Companies Inc)							
7. Mine Location Information					8. Mine ID Number		9. Union		
a) City Orem		b) County Salt Lake		c) State UT		42-02107		No	
10. Primary Mineral Mined Construction Sand & Gravel Mining, N.E.C.				11. Number of Employees					
				a) Total 40		b) Underground		c) Open Pit/Quarry 40	
						d) Mill/Prep Plant 0		e) Other 0	
12. Contractor Name					13. Contractor Union		14. Contractor ID Number		
15. Contractor Address									
a) City		b) County			c) State			d) Zip Code	
16. Number of Contractor Employees									
a) Total		b) Underground			c) Open Pit/Quarry			d) Mill/Prep Plant	
								e) Other	
17. Number of Persons in Mine at Time of Accident					18. Number of Persons Unaccounted for				
a) Mine Employees 26		b) Contractor Employees 0			a) Mine Employees 0		b) Contractor Employees 0		
19. Accident Location 03 - Open Pit							20. Mining Height 60 Feet 0 Inches		
21. Nonfatal Injuries 0		22. Fatal Injuries 1							
23. Victims Information									
Jared Payne									
a) First Name Jared		a) MI	a) Last Name Payne		b) Age 39	c) Regular Job Title Haul Truck Driver		d) Activity at Time of Accident Hauling Material	
Employee Mine Employee									
24. Mining Experience									
a) Total Experience 15 Years 42 Weeks 0 Days			b) Experience at the Mine 0 Years 42 Weeks 0 Days			c) Experience at the Activity at the Time of the Accident 0 Years 42 Weeks 0 Days			d) Experience with Contractor 0 Years 0 Weeks 0 Days
25. Autopsy Performed No		If Yes, Location							
26. Mine Telephone No. (801) 281-7900									
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) The victim was dumping feed material above the feeder, when the haul truck he was operating traveled backwards over the elevated embankment and overturned, landing on the roof of the cab. <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>									
28. Equipment Manufacturer Caterpillar					29. Model 773B				
30. District M6000 - Denver District					32. Field Office M6851 - Salt Lake City UT Field Office			33. Event Number 6781141	
34. Accident Investigator									
First Name Ernesto		MI		Last Name Vasquez					
35. MSHA Person Notified									
First Name Thomas		MI P		Last Name Stefansky			Date/Time Notified 01/19/2021 1:15 PM		
36. Type of Report Initial		37. Name of Preparer			Date Prepared				
		Full Name Peter DelDuca			01/20/2021				
38. Reason for Amendment									