Preliminary Report of Accident

U.S. Department of Labor Mine Safety and Health Administration

PR001 06/03/2021

1. Accident Type	2. Accident Classification	3. Date/Time of Accident	4. Date/Time of Death	5. Fatal Case No	
F - Fatal Injury	06 - Fall of Face, Rib, Pillar or Highwall	06/02/2021 2:30 AM	06/02/2021 3:30 AM	FAI-7013240-1	
6. Mine Information	:	-	-		
a) Mining Company Name: b) Mine Name:	Marion County Coal Resources, I Marion County Mine	nc.			
c) Parent of Mining Company:	ACNR Holdings, Inc				
7. Mine Location Information			8. Mine ID Number	9. Union	
a) City	b) County	c) State	46-01433	Yes	
METZ	Marion	WV			
10. Primary Mineral Mined		11. Number of Employees			
Bituminous Coal Underground Mining		a) Total b) Unde	erground c) Open Pit/Quarry	d) Mill/Prep Plant e) Other	
		462 401		55 6	
12. Contractor Name			13. Contractor Union	14. Contractor ID Number	
15. Contractor Address					
a) City	b) County	c) State	d) Zip Code		
16. Number of Contractor Employ	ees				
a) Total b) Underground		c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other	
17. Number of Persons in Mine at	Time of Accident	18. Number of Persons Unacco	unted for		
a) Mine Employees 8	b) Contractor Employees	a) Mine Employees 0	b) Contractor Employees		
19. Accident Location				20. Mining Height	
01-07 - Underground Advance N	<i>l</i> lining			9 Feet 6 Inches	
21. Nonfatal Injuries	22. Fatal Injuries				
23. Victims Information					

Trenten J Dille							
a) First Name Trenten	a) MI J	a) Last Name Dille	b) Age 25	, .	ar Job Title ection Foreman	d) Activity at Time of Accident Rib bolting	Employee Mine Employee
24. Mining Expe	rience	, .	rience at th		, .	at the Activity at the Time of the Accident	d) Experience with Contractor
5 Years 48 25. Autopsy Pe		Days 2 Yea	rs 44 Week	s 0 Days	2 Years 2 We	eks 0 Days	0 Years 0 Weeks 0 Days
Yes		Charlesto					

26. Mine Telephone No.

(304) 986-6033

27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)

A Section Foreman was fatally injured while installing a rib bolt. He was using a rib drill on the full face continuous mining machine when the corner of the mine rib sheared off and pinned him against the mining machine. The piece of rib that struck the victim consisted of rock and coal, and measured approximately 6 feet wide, 4.5 feet high, and 2 feet thick.

The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer Voest Alpine			29. Model ABM14	
30. District C0300 - Morgantown District			32. Field Office C0301 - Morgantown WV Field Office	33. Event Number 7013240
34. Accident Investigator				
First Name	MI	Last Name		
Nicholas	K	Blevins		
35. MSHA Person Notified				
First Name	MI	Last Name	Date/Time Notified	
William	R	Spens	06/02/2021 3:11 AM	
36. Type of Report	37. Name of	Preparer		
Initial	Full Name Nicholas K Blevins		Date Prepared	
			06/02/2021	