

# Preliminary Report of Accident

U.S. Department of Labor  
Mine Safety and Health Administration



PR001 03/18/2021

<b>1. Accident Type</b> F - Fatal Injury		<b>2. Accident Classification</b> 17 - Machinery		<b>3. Date/Time of Accident</b> 03/12/2021 11:53 AM		<b>4. Date/Time of Death</b> 03/12/2021 10:19 PM		<b>5. Fatal Case No</b> FAI-6490072-1		
<b>6. Mine Information</b>										
<b>a) Mining Company Name:</b>		Gateway Dredging and Contracting LLC								
<b>b) Mine Name:</b>		Dredge Chesterfield								
<b>c) Parent of Mining Company:</b>		David J Bangert et al								
<b>7. Mine Location Information</b>					<b>8. Mine ID Number</b>		<b>9. Union</b>			
<b>a) City</b> Bridgeton		<b>b) County</b> St Louis		<b>c) State</b> MO		23-00889		Yes		
<b>10. Primary Mineral Mined</b> Common Sand Mining				<b>11. Number of Employees</b>			<b>d) Mill/Prep Plant</b>		<b>e) Other</b>	
				<b>a) Total</b> 4	<b>b) Underground</b>		<b>c) Open Pit/Quarry</b>		4	
<b>12. Contractor Name</b>						<b>13. Contractor Union</b>		<b>14. Contractor ID Number</b>		
<b>15. Contractor Address</b>										
<b>a) City</b>		<b>b) County</b>			<b>c) State</b>			<b>d) Zip Code</b>		
<b>16. Number of Contractor Employees</b>										
<b>a) Total</b>		<b>b) Underground</b>			<b>c) Open Pit/Quarry</b>			<b>d) Mill/Prep Plant</b>		<b>e) Other</b>
<b>17. Number of Persons in Mine at Time of Accident</b>					<b>18. Number of Persons Unaccounted for</b>					
<b>a) Mine Employees</b> 4		<b>b) Contractor Employees</b>			<b>a) Mine Employees</b>		<b>b) Contractor Employees</b>			
<b>19. Accident Location</b> 06 - Dredge Mining								<b>20. Mining Height</b>		
								Feet	Inches	
<b>21. Nonfatal Injuries</b>		<b>22. Fatal Injuries</b> 1								
<b>23. Victims Information</b>										
Jonathan S Castloo										
<b>a) First Name</b> Jonathan	<b>a) MI</b> S	<b>a) Last Name</b> Castloo		<b>b) Age</b> 35	<b>c) Regular Job Title</b> Operator		<b>d) Activity at Time of Accident</b> Spud replacement		<b>Employee</b> Mine Employee	
<b>24. Mining Experience</b>										
<b>a) Total Experience</b> 8 Years 2 Weeks 4 Days		<b>b) Experience at the Mine</b> 8 Years 2 Weeks 4 Days			<b>c) Experience at the Activity at the Time of the Accident</b> 8 Years 2 Weeks 4 Days			<b>d) Experience with Contractor</b> Years Weeks Days		
<b>25. Autopsy Performed</b> No		<b>If Yes, Location</b>								
<b>26. Mine Telephone No.</b> (636) 665-5180										
<b>27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)</b> The victim was attempting to insert a safety pin into a hole in a barge spud. The pin was partially inserted into the collar of the hole as the spud continued to lower into the spud well. The victim was struck in the face by the cantilever action of the safety pin.  <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>										
<b>28. Equipment Manufacturer</b> Not listed Pin and Spud were fabricated on site.					<b>29. Model</b>					
<b>30. District</b> C1000 - Madisonville District				<b>32. Field Office</b> C1004 - Rolla MO Field Office			<b>33. Event Number</b> 6490072			
<b>34. Accident Investigator</b>										
<b>First Name</b> Nicholas		<b>MI</b> P	<b>Last Name</b> Dunne							
<b>35. MSHA Person Notified</b>										
<b>First Name</b> Alan		<b>MI</b>	<b>Last Name</b> Fredrick			<b>Date/Time Notified</b> 03/12/2021 12:38 PM				
<b>36. Type of Report</b> Initial		<b>37. Name of Preparer</b>			<b>Date Prepared</b>					
		<b>Full Name</b> Nicholas P Dunne			03/14/2021					
<b>38. Reason for Amendment</b>										