

## Fatality Alert

MINE FATALITY – On October 19, 2021, a 58-year-old mechanic with 17 years of experience was fatality injured when the articulated haul truck bed collapsed on him while he was performing maintenance on the truck.



### Best Practices

- **Securely block from motion** machinery or equipment that has been raised and properly use mechanical blocking devices. Ensure that blocking material is competent, substantial, and adequate to support and stabilize the load.
- **Position yourself in a safe location** and away from potential “red-zone” areas where you can be injured. Observe and follow all warning labels and signs on equipment.
- **Never work under a load that is unsupported or inadequately supported** and never depend on hydraulics to support a load.
- **Outfit haul trucks with a dump box lock bar** that mechanically blocks the bed from coming down.
- **Develop and follow** safe work procedures.
- **Always consult and follow the manufacturer's recommended safe work procedures** for the maintenance task.

This is the 29th fatality reported in 2021, and the 13th classified as “Powered Haulage.”

---

The information provided in this notice is based on preliminary data only and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the fatality.

**Report accidents and hazardous conditions: 1-800-746-1553**

[msha.gov](https://www.msha.gov) | [askmsha@dol.gov](mailto:askmsha@dol.gov) | [@MSHA\\_DOL](https://twitter.com/MSHA_DOL)