

# Preliminary Report of Accident

U.S. Department of Labor  
Mine Safety and Health Administration



PR001 02/18/2022

<b>1. Accident Type</b> F - Fatal Injury		<b>2. Accident Classification</b> 12 - Powered Haulage		<b>3. Date/Time of Accident</b> 02/14/2022 8:48 PM		<b>4. Date/Time of Death</b> 02/15/2022 5:56 PM		<b>5. Fatal Case No</b> FAI-6875415-1	
<b>6. Mine Information</b>									
<b>a) Mining Company Name:</b>		Nevada Gold Mines, LLC							
<b>b) Mine Name:</b>		Cortez District-Underground							
<b>c) Parent of Mining Company:</b>		Newmont Goldcorp Corporation et al							
<b>7. Mine Location Information</b>						<b>8. Mine ID Number</b>		<b>9. Union</b>	
<b>a) City</b> ELKO		<b>b) County</b> Lander		<b>c) State</b> NV		26-02573		No	
<b>10. Primary Mineral Mined</b> Gold Ore Mining, N.E.C.				<b>11. Number of Employees</b>					
				<b>a) Total</b> 278		<b>b) Underground</b> 255		<b>c) Open Pit/Quarry</b> 0	
								<b>d) Mill/Prep Plant</b> 0	
								<b>e) Other</b> 23	
<b>12. Contractor Name</b>						<b>13. Contractor Union</b>		<b>14. Contractor ID Number</b>	
<b>15. Contractor Address</b>									
<b>a) City</b>		<b>b) County</b>			<b>c) State</b>			<b>d) Zip Code</b>	
<b>16. Number of Contractor Employees</b>									
<b>a) Total</b>		<b>b) Underground</b>			<b>c) Open Pit/Quarry</b>			<b>d) Mill/Prep Plant</b>	
								<b>e) Other</b>	
<b>17. Number of Persons in Mine at Time of Accident</b>					<b>18. Number of Persons Unaccounted for</b>				
<b>a) Mine Employees</b> 40		<b>b) Contractor Employees</b>			<b>a) Mine Employees</b> 0		<b>b) Contractor Employees</b>		
<b>19. Accident Location</b> 01 - Underground								<b>20. Mining Height</b> 60 Feet 0 Inches	
<b>21. Nonfatal Injuries</b> 0		<b>22. Fatal Injuries</b> 1							
<b>23. Victims Information</b>									
Marissa Hill									
<b>a) First Name</b> Marissa		<b>a) MI</b>	<b>a) Last Name</b> Hill		<b>b) Age</b> 34	<b>c) Regular Job Title</b> Maintenance Technician		<b>d) Activity at Time of Accident</b> Lube Truck Operator	
<b>Employee</b> Mine Employee									
<b>24. Mining Experience</b>									
<b>a) Total Experience</b> 10 Years 12 Weeks 0 Days			<b>b) Experience at the Mine</b> 10 Years 12 Weeks 0 Days			<b>c) Experience at the Activity at the Time of the Accident</b> 10 Years 12 Weeks 0 Days			<b>d) Experience with Contractor</b> 0 Years 0 Weeks 0 Days
<b>25. Autopsy Performed</b> No		<b>If Yes, Location</b>							
<b>26. Mine Telephone No.</b> (775) 468-4401									
<b>27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)</b> A miner died when the lube truck she was driving fell approximately 60 feet down a stope to the mine floor below.  <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>									
<b>28. Equipment Manufacturer</b> Getman					<b>29. Model</b> A-64				
<b>30. District</b> M7000 - Vacaville District					<b>32. Field Office</b> M7851 - Elko NV Field Office			<b>33. Event Number</b> 6875415	
<b>34. Accident Investigator</b>									
<b>First Name</b> Benjamin		<b>MI</b> C	<b>Last Name</b> Burns						
<b>35. MSHA Person Notified</b>									
<b>First Name</b> Melvin		<b>MI</b> K	<b>Last Name</b> Palmer			<b>Date/Time Notified</b> 02/15/2022 1:01 AM			
<b>36. Type of Report</b> Initial		<b>37. Name of Preparer</b> <b>Full Name</b> Leanne C Russell			<b>Date Prepared</b> 02/15/2022				
<b>38. Reason for Amendment</b>									