Preliminary Report of Accident



PR001 01/14/2022

1. Accident Type	2. Accident Classification	3. Date/Time of Accident	4. Date/Time of Death	5. Fatal Case No
F - Fatal Injury	05 - Falling, Rolling or Sliding Rock /Material	01/11/2022 2:45 PM	01/11/2022 2:45 PM	FAI-7020751-1
6. Mine Information a) Mining Company Name: b) Mine Name: c) Parent of Mining Company:	Nally & Hamilton Enterprises Inc Colmar Thomas R Hamilton et al	1		
7. Mine Location Information			8. Mine ID Number	9. Union
a) City Pineville	b) County Bell	c) State KY	15-19884	No
10. Primary Mineral Mined		11. Number of Employees	•	•
Bituminous		a) Total b) Underg	ground c) Open Pit/Quarry 20	d) Mill/Prep Plant e) Other 0 0
12. Contractor Name			13. Contractor Union	14. Contractor ID Number
15. Contractor Address a) City	b) County	c) State	d) Zip Code	
16. Number of Contractor Employe	ees			
a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
17. Number of Persons in Mine at a) Mine Employeesk1212	Time of Accident b) Contractor Employees 0	18. Number of Persons Unaccoun a) Mine Employees 0	ted for b) Contractor Employees 0	
19. Accident Location 03 - Open Pit				20. Mining Height Feet Inches
21. Nonfatal Injuries	22. Fatal Injuries			·
23. Victims Information				
Cecil T Collett				
a) First Name a) MI a) La	ast Name b) Age c) Regular Jo ollett 32 Blaster and		at Time of Accident f pickup truck	Employee Mine Employee
a) First Name a) MI a) La	b) Experience at the Mine		f pickup truck Time of the Accident d) Exp	
a) First Name a) MI a) La Cecil T Co 24. Mining Experience a) Total Experience	b) Experience at the Mine	Equipment Operator Driver of C) Experience at the Activity at the	f pickup truck Time of the Accident d) Exp	Mine Employee
a) First Name a) MI a) La Cecil T Co 24. Mining Experience a) Total Experience 11 Years 0 Weeks 0 Days 25. Autopsy Performed No 26. Mine Telephone No.	b) Experience at the Mine 8 Years 0 Weeks 0 Days	Equipment Operator Driver of C) Experience at the Activity at the	f pickup truck Time of the Accident d) Exp	Mine Employee
a) First Name a) MI a) La Cecil T Co 24. Mining Experience a) Total Experience 11 Years 0 Weeks 0 Days 25. Autopsy Performed No 26. Mine Telephone No. (606) 337-9043	b) Experience at the Mine 8 Years 0 Weeks 0 Days If Yes, Location	Equipment Operator Driver of c) Experience at the Activity at the 11 Years 0 Weeks 0 Days	f pickup truck Time of the Accident d) Exp 0 Ye	Mine Employee
a) First Name a) MI a) La Cecil T Co 24. Mining Experience a) Total Experience 11 Years 0 Weeks 0 Days 25. Autopsy Performed No 26. Mine Telephone No. (606) 337-9043 27. Description of Accident (include	b) Experience at the Mine 8 Years 0 Weeks 0 Days If Yes, Location de equipment involved, the exact lo	Equipment Operator Driver of c) Experience at the Activity at the 11 Years 0 Weeks 0 Days cation in the mine, and status and m	f pickup truck Time of the Accident d) Exp 0 Ye	Mine Employee erience with Contractor bars 0 Weeks 0 Days
a) First Name a) MI a) La Cecil T Co 24. Mining Experience a) Total Experience 11 Years 0 Weeks 0 Days 25. Autopsy Performed No 26. Mine Telephone No. (606) 337-9043 27. Description of Accident (includ A large tree fell from a highwall s	bllett 32 Blaster and b) Experience at the Mine 8 Years 0 Weeks 0 Days If Yes, Location de equipment involved, the exact lo striking the cab of a pick-up truck, resu	Equipment Operator Driver of c) Experience at the Activity at the 11 Years 0 Weeks 0 Days cation in the mine, and status and m liting in a fatal injury to the truck driver	f pickup truck Time of the Accident d) Exp 0 Ye ecovery operations)	Mine Employee erience with Contractor ears 0 Weeks 0 Days
a) First Name a) MI a) La Cecil T Co 24. Mining Experience a) Total Experience 11 Years 0 Weeks 0 Days 25. Autopsy Performed No 26. Mine Telephone No. (606) 337-9043 27. Description of Accident (includ A large tree fell from a highwall s The information provided in this of	bllett 32 Blaster and b) Experience at the Mine 8 Years 0 Weeks 0 Days If Yes, Location de equipment involved, the exact lo striking the cab of a pick-up truck, resu	Equipment Operator Driver of c) Experience at the Activity at the 11 Years 0 Weeks 0 Days cation in the mine, and status and m liting in a fatal injury to the truck driver	f pickup truck Time of the Accident d) Exp 0 Ye ecovery operations) and a serious injury to the passenger.	Mine Employee erience with Contractor ears 0 Weeks 0 Days
 a) First Name a) MI	bllett 32 Blaster and b) Experience at the Mine 8 Years 0 Weeks 0 Days If Yes, Location de equipment involved, the exact lo striking the cab of a pick-up truck, resu	Equipment Operator Driver of c) Experience at the Activity at the 11 Years 0 Weeks 0 Days cation in the mine, and status and re ulting in a fatal injury to the truck driver NLY and does not represent final deter 29. Model	f pickup truck Time of the Accident d) Exp 0 Ye ecovery operations) and a serious injury to the passenger. mination regarding the nature of the in	Mine Employee erience with Contractor ears 0 Weeks 0 Days
 a) First Name a) MI	bllett 32 Blaster and b) Experience at the Mine 8 Years 0 Weeks 0 Days If Yes, Location de equipment involved, the exact lo striking the cab of a pick-up truck, resu	Equipment Operator Driver of c) Experience at the Activity at the 11 Years 0 Weeks 0 Days cation in the mine, and status and re liting in a fatal injury to the truck driver NLY and does not represent final deter 29. Model F-250 32. Field Office	f pickup truck Time of the Accident d) Exp 0 Ye ecovery operations) and a serious injury to the passenger. mination regarding the nature of the in	Mine Employee erience with Contractor ears 0 Weeks 0 Days cident or conclusions regarding the 33. Event Number
 a) First Name a) Mi a) La Cecil Cecil T Cecil 24. Mining Experience a) Total Experience a) Total Experience 11 Years 0 Weeks 0 Days 25. Autopsy Performed No 26. Mine Telephone No. (606) 337-9043 27. Description of Accident (include A large tree fell from a highwall structure for the accident. 28. Equipment Manufacturer Ford (Ford Motor Co.) 30. District	bllett 32 Blaster and b) Experience at the Mine 8 Years 0 Weeks 0 Days If Yes, Location de equipment involved, the exact lo striking the cab of a pick-up truck, resu	Equipment Operator Driver of c) Experience at the Activity at the 11 Years 0 Weeks 0 Days cation in the mine, and status and re liting in a fatal injury to the truck driver NLY and does not represent final deter 29. Model F-250 32. Field Office	f pickup truck Time of the Accident d) Exp 0 Ye ecovery operations) and a serious injury to the passenger. mination regarding the nature of the in	Mine Employee erience with Contractor ears 0 Weeks 0 Days cident or conclusions regarding the 33. Event Number
 a) First Name a) Mi	b) Experience at the Mine 8 Years 0 Weeks 0 Days If Yes, Location de equipment involved, the exact lo striking the cab of a pick-up truck, resunction MI Last Name	Equipment Operator Driver of c) Experience at the Activity at the 11 Years 0 Weeks 0 Days cation in the mine, and status and re liting in a fatal injury to the truck driver NLY and does not represent final deter 29. Model F-250 32. Field Office	f pickup truck Time of the Accident d) Exp 0 Ye ecovery operations) and a serious injury to the passenger. mination regarding the nature of the in	Mine Employee erience with Contractor ears 0 Weeks 0 Days cident or conclusions regarding the 33. Event Number
 a) First Name a) Mi	b) Experience at the Mine 8 Years 0 Weeks 0 Days If Yes, Location de equipment involved, the exact lo striking the cab of a pick-up truck, resunction MI Last Name	Equipment Operator Driver of c) Experience at the Activity at the 11 Years 0 Weeks 0 Days cation in the mine, and status and re liting in a fatal injury to the truck driver NLY and does not represent final deter 29. Model F-250 32. Field Office	f pickup truck Time of the Accident d) Exp 0 Ye 0 Ye ecovery operations) and a serious injury to the passenger. mination regarding the nature of the in office tified	Mine Employee erience with Contractor ears 0 Weeks 0 Days cident or conclusions regarding the 33. Event Number
 a) First Name a) Mi	b) Experience at the Mine 8 Years 0 Weeks 0 Days If Yes, Location de equipment involved, the exact lo striking the cab of a pick-up truck, resunction totice is based on preliminary data Ol MI Last Name Brock MI Last Name	Equipment Operator Driver of c) Experience at the Activity at the 11 Years 0 Weeks 0 Days cation in the mine, and status and re- liting in a fatal injury to the truck driver NLY and does not represent final deter 29. Model F-250 32. Field Office C0701 - Barbourville KY Field C Date/Time No	f pickup truck Time of the Accident d) Exp 0 Ye 0 Ye ecovery operations) and a serious injury to the passenger. mination regarding the nature of the in office tified	Mine Employee erience with Contractor ears 0 Weeks 0 Days cident or conclusions regarding the 33. Event Number
 a) First Name a) Mi	b) Experience at the Mine 8 Years 0 Weeks 0 Days If Yes, Location de equipment involved, the exact lo striking the cab of a pick-up truck, resunction notice is based on preliminary data Of MI Last Name Brock MI Last Name Hinkle 37. Name of Preparer Full Name	Equipment Operator Driver of c) Experience at the Activity at the 11 Years 0 Weeks 0 Days cation in the mine, and status and re ilting in a fatal injury to the truck driver NLY and does not represent final deter 29. Model F-250 32. Field Office C0701 - Barbourville KY Field C Date/Time No 01/11/2022 3:1 Date Prepared	f pickup truck Time of the Accident d) Exp 0 Ye 0 Ye ecovery operations) and a serious injury to the passenger. mination regarding the nature of the in office tified	Mine Employee erience with Contractor ears 0 Weeks 0 Days cident or conclusions regarding the 33. Event Number

Preliminary Report of Accident



PR001 01/14/2022

1. Accident Type F - Fatal Injury	2. Accident Classification 05 - Falling, Rolling or Sliding Rock /Material	3. Date/Time of Accident 01/11/2022 2:45 PM	4. Date/Time of Death	5. Fatal Case No FAI-7020751-1
6. Mine Information a) Mining Company Name: b) Mine Name: c) Parent of Mining Company:	Nally & Hamilton Enterprises Inc Colmar Thomas R Hamilton et al			
7. Mine Location Information a) City Pineville	b) County Bell	c) State KY	8. Mine ID Number 15-19884	9. Union No
10. Primary Mineral Mined Bituminous		11. Number of Employeesa) Totalb) Underg20	ground c) Open Pit/Quarry 20	d) Mill/Prep Plant e) Other 0 0
12. Contractor Name			13. Contractor Union	14. Contractor ID Number
15. Contractor Address a) City	b) County	c) State	d) Zip Code	
16. Number of Contractor Employe a) Total	ees b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
17. Number of Persons in Mine at a) Mine Employeesk1212	Time of Accident o) Contractor Employees 0	18. Number of Persons Unaccour a) Mine Employees 0	ted for b) Contractor Employees 0	
19. Accident Location 03 - Open Pit				20. Mining Height Feet Inches
21. Nonfatal Injuries	22. Fatal Injuries			
23. Victims Information				
Joshua D Pendleton				
		lar Job Title d) Activity at Ti ment Operator Passenger of	me of Accident pickup truck	Employee Mine Employee
a) First Name a) MI a)	,		Time of the Accident d) Ex	
a) First Name a) MI a) Joshua D 24. Mining Experience a) Total Experience	Pendleton 45 Equip	c) Experience at the Activity at the	Time of the Accident d) Ex	Mine Employee
a) First Name a) MI a) Joshua D 24. Mining Experience a) Total Experience 8 Years 0 Weeks 0 Days	Pendleton 45 Equip b) Experience at the Mine 0 Years 17 Weeks 2 Days	c) Experience at the Activity at the	Time of the Accident d) Ex	Mine Employee
a) First Name a) MI a) Joshua D 24. Mining Experience a) Total Experience 8 Years 0 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (606) 337-9043 27. Description of Accident (includ	Pendleton 45 Equip b) Experience at the Mine 0 Years 17 Weeks 2 Days If Yes, Location	c) Experience at the Activity at the	Time of the Accident d) Ex 0 Y ecovery operations)	Mine Employee perience with Contractor ears 0 Weeks 0 Days
a) First Name a) MI a) Joshua D 24. Mining Experience a) Total Experience 8 Years 0 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (606) 337-9043 27. Description of Accident (includ A large tree fell from a highwall s	Pendleton 45 Equip b) Experience at the Mine 0 Years 17 Weeks 2 Days If Yes, Location de equipment involved, the exact lostriking the cab of a pick-up truck, results	ment Operator Passenger of c) Experience at the Activity at the 0 Years 17 Weeks 2 Days pocation in the mine, and status and r	Pickup truck Time of the Accident O Y O Y Control Contro Control Control Control Control Control Control Control Contr	Mine Employee perience with Contractor ears 0 Weeks 0 Days
a) First Name a) MI a) Joshua D 24. Mining Experience a) Total Experience a) Total Experience 8 Years 0 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (606) 337-9043 27. Description of Accident (include A large tree fell from a highwall s The information provided in this A	Pendleton 45 Equip b) Experience at the Mine 0 Years 17 Weeks 2 Days If Yes, Location de equipment involved, the exact lostriking the cab of a pick-up truck, results	ment Operator Passenger of c) Experience at the Activity at the 0 Years 17 Weeks 2 Days Decation in the mine, and status and r ulting in a fatal injury to the truck driver	Pickup truck Time of the Accident O Y O Y Control Contro Control Control Control Control Control Control Control Contr	Mine Employee perience with Contractor ears 0 Weeks 0 Days
a) First Name a) MI a) Joshua D 24. Mining Experience a) Total Experience 8 Years 0 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (606) 337-9043 27. Description of Accident (includ A large tree fell from a highwall s The information provided in this is cause of the accident. 28. Equipment Manufacturer	Pendleton 45 Equip b) Experience at the Mine 0 Years 17 Weeks 2 Days If Yes, Location de equipment involved, the exact lostriking the cab of a pick-up truck, results	ment Operator Passenger of c) Experience at the Activity at the 0 Years 17 Weeks 2 Days o Years 17 Weeks 2 Days 0 Years 17 Weeks 2 Days ocation in the mine, and status and r 0 Years 17 Weeks 2 Days ocation in the mine, and status and r 0 Years 17 Weeks 2 Days ocation in the mine, and status and r 0 Years 17 Weeks 2 Days Output 0 Years 17 Weeks 2 Days ocation in the mine, and status and r 0 Years 17 Weeks 2 Days Output 0 Years 17 Weeks 2 Days ocation in the mine, and status and r 0 Years 17 Weeks 2 Days Output 0 Years 17 Weeks 2 Days ocation in the mine, and status and r 0 Years 17 Weeks 2 Days VLY and does not represent final determined by the truck driver 0 Years 17 Weeks 2 Days 29. Model 0 Years 17 Weeks 2 Days	Time of the Accident d) Ex 0 Y ecovery operations) and a serious injury to the passenger rmination regarding the nature of the i	Mine Employee perience with Contractor ears 0 Weeks 0 Days
 a) First Name a) MI a) Joshua D 24. Mining Experience a) Total Experience 8 Years 0 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (606) 337-9043 27. Description of Accident (include A large tree fell from a highwall st <i>The information provided in this in cause of the accident.</i> 28. Equipment Manufacturer Ford (Ford Motor Co.) 30. District 	Pendleton 45 Equip b) Experience at the Mine 0 Years 17 Weeks 2 Days If Yes, Location de equipment involved, the exact lostriking the cab of a pick-up truck, results	ment Operator Passenger of c) Experience at the Activity at the 0 Years 17 Weeks 2 Days ocation in the mine, and status and r ulting in a fatal injury to the truck driver NLY and does not represent final deter 29. Model F-250 32. Field Office	Time of the Accident d) Ex 0 Y ecovery operations) and a serious injury to the passenger rmination regarding the nature of the i	Mine Employee perience with Contractor ears 0 Weeks 0 Days ncident or conclusions regarding the 33. Event Number
a) First Name a) MI a) Joshua D 24. Mining Experience a) Total Experience a) Total Experience 8 Years 0 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (606) 337-9043 27. Description of Accident (include A large tree fell from a highwall s <i>The information provided in this ic cause of the accident.</i> 28. Equipment Manufacturer Ford (Ford Motor Co.) 30. District C0700 - Barbourville District 34. Accident Investigator First Name	Pendleton 45 Equip b) Experience at the Mine 0 Years 17 Weeks 2 Days If Yes, Location de equipment involved, the exact to striking the cab of a pick-up truck, resunctice is based on preliminary data O MI Last Name	ment Operator Passenger of c) Experience at the Activity at the 0 Years 17 Weeks 2 Days ocation in the mine, and status and r ulting in a fatal injury to the truck driver NLY and does not represent final deter 29. Model F-250 32. Field Office	Time of the Accident d) Ex 0 Y ecovery operations) and a serious injury to the passenger rmination regarding the nature of the in office	Mine Employee perience with Contractor ears 0 Weeks 0 Days ncident or conclusions regarding the 33. Event Number
 a) First Name a) MI a) Joshua D 24. Mining Experience a) Total Experience 8 Years 0 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (606) 337-9043 27. Description of Accident (include A large tree fell from a highwall s The information provided in this is cause of the accident. 28. Equipment Manufacturer Ford (Ford Motor Co.) 30. District C0700 - Barbourville District 34. Accident Investigator First Name Silas 35. MSHA Person Notified First Name 	Pendleton 45 Equip b) Experience at the Mine 0 Years 17 Weeks 2 Days 0 Years 17 Weeks 2 Days If Yes, Location	ment Operator Passenger of c) Experience at the Activity at the 0 Years 17 Weeks 2 Days ocation in the mine, and status and r ulting in a fatal injury to the truck driver NLY and does not represent final deter 29. Model F-250 32. Field Office C0701 - Barbourville KY Field C	Time of the Accident d) Ex 0 Y ecovery operations) and a serious injury to the passenger rmination regarding the nature of the in office	Mine Employee perience with Contractor ears 0 Weeks 0 Days ncident or conclusions regarding the 33. Event Number