

# Preliminary Report of Accident

U.S. Department of Labor  
Mine Safety and Health Administration



PR001 02/07/2022

<b>1. Accident Type</b> F - Fatal Injury	<b>2. Accident Classification</b> 12 - Powered Haulage	<b>3. Date/Time of Accident</b> 01/26/2022 7:45 AM	<b>4. Date/Time of Death</b> 01/26/2022 12:45 PM	<b>5. Fatal Case No</b> FAI-6886500-1
<b>6. Mine Information</b>				
<b>a) Mining Company Name:</b> Ouachita Rock, Inc.		<b>b) Mine Name:</b> Ouachita Rock Portable		
<b>c) Parent of Mining Company:</b> Danny Hansbrough				
<b>7. Mine Location Information</b>			<b>8. Mine ID Number</b> 03-01867	<b>9. Union</b> No
<b>a) City</b> MENA	<b>b) County</b> Polk	<b>c) State</b> AR		
<b>10. Primary Mineral Mined</b> Gravel Mining		<b>11. Number of Employees</b>		
		<b>a) Total</b> 3	<b>b) Underground</b>	<b>c) Open Pit/Quarry</b> 3
			<b>d) Mill/Prep Plant</b> 0	<b>e) Other</b>
<b>12. Contractor Name</b>			<b>13. Contractor Union</b>	<b>14. Contractor ID Number</b>
<b>15. Contractor Address</b>				
<b>a) City</b>	<b>b) County</b>	<b>c) State</b>	<b>d) Zip Code</b>	
<b>16. Number of Contractor Employees</b>				
<b>a) Total</b>	<b>b) Underground</b>	<b>c) Open Pit/Quarry</b>	<b>d) Mill/Prep Plant</b>	<b>e) Other</b>
<b>17. Number of Persons in Mine at Time of Accident</b>		<b>18. Number of Persons Unaccounted for</b>		
<b>a) Mine Employees</b> 3	<b>b) Contractor Employees</b>	<b>a) Mine Employees</b> 0	<b>b) Contractor Employees</b>	
<b>19. Accident Location</b> 03 - Open Pit				<b>20. Mining Height</b> 15 Feet 0 Inches
<b>21. Nonfatal Injuries</b> 0	<b>22. Fatal Injuries</b> 1			

**23. Victims Information**

<b>Patrick Green</b>						
<b>a) First Name</b> Patrick	<b>a) MI</b>	<b>a) Last Name</b> Green	<b>b) Age</b> 54	<b>c) Regular Job Title</b> Front End Loader Operator	<b>d) Activity at Time of Accident</b> Loading Customer trucks	<b>Employee</b> Mine Employee
<b>24. Mining Experience</b>						
<b>a) Total Experience</b> 2 Years 39 Weeks Days		<b>b) Experience at the Mine</b> 1 Years 3 Weeks Days		<b>c) Experience at the Activity at the Time of the Accident</b> 0 Years 0 Weeks Days		<b>d) Experience with Contractor</b> 0 Years 0 Weeks Days
<b>25. Autopsy Performed</b>		<b>If Yes, Location</b>				

**26. Mine Telephone No.**

(479) 394-1030

**27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)**

A front end loader operator went under a dump truck to resolve a park brake issue and was fatally injured when the tire of the dump truck rolled onto him.

*The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.*

<b>28. Equipment Manufacturer</b> Western Star		<b>29. Model</b> 1988		
<b>30. District</b> M5000 - Dallas District		<b>32. Field Office</b> M5871 - Little Rock AR Field Office		<b>33. Event Number</b> 6886500
<b>34. Accident Investigator</b>				
<b>First Name</b> William	<b>MI</b> B.	<b>Last Name</b> Clark		
<b>35. MSHA Person Notified</b>				
<b>First Name</b> Jim	<b>MI</b>	<b>Last Name</b> Dobyns	<b>Date/Time Notified</b> 01/26/2022 10:21 AM	
<b>36. Type of Report</b> Initial		<b>37. Name of Preparer</b>		<b>Date Prepared</b>
		<b>Full Name</b> William B. Clark		<b>Date Prepared</b> 01/27/2022
<b>38. Reason for Amendment</b>				