

Fatality Alert

MINE FATALITY – On June 17, 2022, a contract miner died when the compactor he was operating overturned, pinning him beneath the cab. As the miner was backing up, the left tire went off the edge of a four-foot embankment, causing the compactor to overturn.



Best Practices

- **Wear seat belts** at all times when operating equipment.
- **Train miners** to perform tasks safely, and to recognize potential hazards.

This is the 13th fatality reported in 2022, and the 4th classified as “Machinery.”

The information provided in this notice is based on preliminary data only and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the fatality.

Report accidents and hazardous conditions: 1-800-746-1553

[msha.gov](https://www.msha.gov) | askmsha@dol.gov | [@MSHA_DOL](https://twitter.com/MSHA_DOL)