## **Preliminary Report of Accident**

## Mine Safety and Health Administration

## PR001 10/14/2022

1. Accident Type				
F - Fatal Injury	2. Accident Classification 21 - Other Accident Engulfment	3. Date/Time of Accident 10/07/2022 8:40 AM	<b>4. Date/Time of Death</b> 10/07/2022 9:23 AM	<b>5. Fatal Case No</b> FAI-6923436-1
Mine Information     a) Mining Company Name:     b) Mine Name:     c) Parent of Mining Company:	J R Vinagro Corporation Portable 11 Joseph Vinagro			
7. Mine Location Information			8. Mine ID Number	9. Union
a) City Tiverton	<b>b) County</b> Newport	c) State RI	37-00243	No
10. Primary Mineral Mined		11. Number of Employees		
Crushed & Broken Granite Minin	ng	a) Total b) Under	ground c) Open Pit/Quarry 8	d) Mill/Prep Plant e) Other
12. Contractor Name			13. Contractor Union	14. Contractor ID Number
15. Contractor Address			<u>'</u>	<u>'</u>
a) City	b) County	c) State	d) Zip Code	
16. Number of Contractor Employ	ees			
a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
17. Number of Persons in Mine at a) Mine Employees I	Time of Accident b) Contractor Employees	18. Number of Persons Unaccour a) Mine Employees	nted for b) Contractor Employees	
19. Accident Location 03 - Open Pit		'		20. Mining Height 45 Feet 0 Inches
21. Nonfatal Injuries	22. Fatal Injuries			1
<u> </u>	'			
23. Victims Information				
Selvin M Ovando Gamez				
		ular Job Title d) Activity at Time	of Accident	Employee
'				
Selvin M C	, , ,		ge from air classifier.	Mine Employee
Selvin M C  24. Mining Experience	Ovando Gamez 29 Lab	orer Clearing blocka	ge from air classifier.	Mine Employee
Selvin M C  24. Mining Experience a) Total Experience	b) Experience at the Mine	c) Experience at the Activity at the	ge from air classifier.  Time of the Accident d) Ex	Mine Employee
Selvin M C  24. Mining Experience	Ovando Gamez 29 Lab	orer Clearing blocka	ge from air classifier.  Time of the Accident d) Ex	Mine Employee
Selvin M C  24. Mining Experience a) Total Experience 5 Years 0 Weeks 0 Days  25. Autopsy Performed No  26. Mine Telephone No.	b) Experience at the Mine 5 Years 0 Weeks 0 Days	c) Experience at the Activity at the	ge from air classifier.  Time of the Accident d) Ex	Mine Employee
Selvin M C  24. Mining Experience a) Total Experience 5 Years 0 Weeks 0 Days  25. Autopsy Performed No  26. Mine Telephone No. (401) 943-7100	by Experience at the Mine 5 Years 0 Weeks 0 Days  If Yes, Location	orer Clearing blockar c) Experience at the Activity at the 5 Years 0 Weeks 0 Days	ge from air classifier.  Time of the Accident d) Ex 0 Y	Mine Employee
Selvin M C  24. Mining Experience a) Total Experience 5 Years 0 Weeks 0 Days  25. Autopsy Performed No  26. Mine Telephone No. (401) 943-7100  27. Description of Accident (include)	by Experience at the Mine 5 Years 0 Weeks 0 Days  If Yes, Location	c) Experience at the Activity at the 5 Years 0 Weeks 0 Days	ge from air classifier.  Time of the Accident d) Ex 0 Y	Mine Employee
Selvin M C  24. Mining Experience a) Total Experience 5 Years 0 Weeks 0 Days  25. Autopsy Performed No  26. Mine Telephone No. (401) 943-7100  27. Description of Accident (included A miner was fatally injured when	b) Experience at the Mine 5 Years 0 Weeks 0 Days  If Yes, Location  de equipment involved, the exact lend to the entered an air classifier and was	c) Experience at the Activity at the 5 Years 0 Weeks 0 Days	ge from air classifier.  Time of the Accident d) Ex 0 Y	Mine Employee  perience with Contractor  /ears 0 Weeks 0 Days
Selvin M C  24. Mining Experience a) Total Experience 5 Years 0 Weeks 0 Days  25. Autopsy Performed No  26. Mine Telephone No. (401) 943-7100  27. Description of Accident (included in the information provided in this	b) Experience at the Mine 5 Years 0 Weeks 0 Days  If Yes, Location  de equipment involved, the exact lend to the entered an air classifier and was	c) Experience at the Activity at the 5 Years 0 Weeks 0 Days  cocation in the mine, and status and engulfed by material.	ge from air classifier.  Time of the Accident d) Ex 0 Y	Mine Employee  perience with Contractor  /ears 0 Weeks 0 Days
Selvin M C  24. Mining Experience a) Total Experience 5 Years 0 Weeks 0 Days  25. Autopsy Performed No  26. Mine Telephone No. (401) 943-7100  27. Description of Accident (included A miner was fatally injured when the information provided in this cause of the accident.  28. Equipment Manufacturer	b) Experience at the Mine 5 Years 0 Weeks 0 Days  If Yes, Location  de equipment involved, the exact lend to the entered an air classifier and was	c) Experience at the Activity at the 5 Years 0 Weeks 0 Days  ocation in the mine, and status and engulfed by material.  ONLY and does not represent final determined to the status and determi	ge from air classifier.  Time of the Accident d) Ex 0 Y  recovery operations)  rmination regarding the nature of the 1	Mine Employee  perience with Contractor  /ears 0 Weeks 0 Days
Selvin M C  24. Mining Experience a) Total Experience 5 Years 0 Weeks 0 Days  25. Autopsy Performed No  26. Mine Telephone No. (401) 943-7100  27. Description of Accident (includent A miner was fatally injured when The information provided in this cause of the accident.  28. Equipment Manufacturer Not listed Fisher Industries  30. District M2000 - Warrendale District	b) Experience at the Mine 5 Years 0 Weeks 0 Days  If Yes, Location  de equipment involved, the exact lend to the entered an air classifier and was	c) Experience at the Activity at the 5 Years 0 Weeks 0 Days  cocation in the mine, and status and engulfed by material.  DNLY and does not represent final determined to the status and status and status and sengulfed by material.  29. Model 13FT Air Seperator  32. Field Office	ge from air classifier.  Time of the Accident d) Ex 0 Y  recovery operations)  rmination regarding the nature of the 1	Mine Employee  perience with Contractor  fears 0 Weeks 0 Days  incident or conclusions regarding the  33. Event Number
Selvin M C  24. Mining Experience a) Total Experience 5 Years 0 Weeks 0 Days  25. Autopsy Performed No  26. Mine Telephone No. (401) 943-7100  27. Description of Accident (included A miner was fatally injured when the information provided in this cause of the accident.  28. Equipment Manufacturer Not listed Fisher Industries  30. District	b) Experience at the Mine 5 Years 0 Weeks 0 Days  If Yes, Location  de equipment involved, the exact lend to the entered an air classifier and was	c) Experience at the Activity at the 5 Years 0 Weeks 0 Days  cocation in the mine, and status and engulfed by material.  DNLY and does not represent final determined to the status and status and status and sengulfed by material.  29. Model 13FT Air Seperator  32. Field Office	ge from air classifier.  Time of the Accident d) Ex 0 Y  recovery operations)  rmination regarding the nature of the 1	Mine Employee  perience with Contractor  fears 0 Weeks 0 Days  incident or conclusions regarding the  33. Event Number
Selvin M C  24. Mining Experience a) Total Experience 5 Years 0 Weeks 0 Days  25. Autopsy Performed No  26. Mine Telephone No. (401) 943-7100  27. Description of Accident (includent A miner was fatally injured when the information provided in this cause of the accident.  28. Equipment Manufacturer Not listed Fisher Industries  30. District M2000 - Warrendale District  34. Accident Investigator	b) Experience at the Mine 5 Years 0 Weeks 0 Days  If Yes, Location  de equipment involved, the exact In the entered an air classifier and was notice is based on preliminary data Company of the exact Inc.	c) Experience at the Activity at the 5 Years 0 Weeks 0 Days  cocation in the mine, and status and engulfed by material.  DNLY and does not represent final determined to the status and status and status and sengulfed by material.  29. Model 13FT Air Seperator  32. Field Office	ge from air classifier.  Time of the Accident d) Ex 0 Y  recovery operations)  rmination regarding the nature of the	Mine Employee  perience with Contractor  fears 0 Weeks 0 Days  incident or conclusions regarding the  33. Event Number
Selvin M C  24. Mining Experience a) Total Experience 5 Years 0 Weeks 0 Days  25. Autopsy Performed No  26. Mine Telephone No. (401) 943-7100  27. Description of Accident (included A miner was fatally injured when the information provided in this cause of the accident.  28. Equipment Manufacturer Not listed Fisher Industries  30. District M2000 - Warrendale District  34. Accident Investigator First Name	b) Experience at the Mine 5 Years 0 Weeks 0 Days  If Yes, Location  de equipment involved, the exact In the entered an air classifier and was notice is based on preliminary data C	c) Experience at the Activity at the 5 Years 0 Weeks 0 Days  cocation in the mine, and status and engulfed by material.  DNLY and does not represent final determined to the status and status and status and sengulfed by material.  29. Model 13FT Air Seperator  32. Field Office	ge from air classifier.  Time of the Accident d) Ex 0 Y  recovery operations)  rmination regarding the nature of the	Mine Employee  perience with Contractor  fears 0 Weeks 0 Days  incident or conclusions regarding the  33. Event Number
Selvin M C  24. Mining Experience a) Total Experience 5 Years 0 Weeks 0 Days  25. Autopsy Performed No  26. Mine Telephone No. (401) 943-7100  27. Description of Accident (includent A miner was fatally injured when The information provided in this cause of the accident.  28. Equipment Manufacturer Not listed Fisher Industries  30. District M2000 - Warrendale District  34. Accident Investigator First Name Arthur	b) Experience at the Mine 5 Years 0 Weeks 0 Days  If Yes, Location  de equipment involved, the exact In the entered an air classifier and was notice is based on preliminary data C	c) Experience at the Activity at the 5 Years 0 Weeks 0 Days  cocation in the mine, and status and engulfed by material.  DNLY and does not represent final determined to the status and status and status and sengulfed by material.  29. Model 13FT Air Seperator  32. Field Office	recovery operations)  rmination regarding the nature of the a	Mine Employee  perience with Contractor  fears 0 Weeks 0 Days  incident or conclusions regarding the  33. Event Number
Selvin M C  24. Mining Experience a) Total Experience 5 Years 0 Weeks 0 Days  25. Autopsy Performed No  26. Mine Telephone No. (401) 943-7100  27. Description of Accident (includent A miner was fatally injured when the information provided in this cause of the accident.  28. Equipment Manufacturer Not listed Fisher Industries  30. District M2000 - Warrendale District  34. Accident Investigator First Name Arthur  35. MSHA Person Notified	b) Experience at the Mine 5 Years 0 Weeks 0 Days  If Yes, Location  de equipment involved, the exact leads to be entered an air classifier and was notice is based on preliminary data Communication.  MI Last Name D Wall	c) Experience at the Activity at the 5 Years 0 Weeks 0 Days  cocation in the mine, and status and engulfed by material.  DNLY and does not represent final determined to the mine of the m	ge from air classifier.  Time of the Accident d) Ex 0 Y  recovery operations)  rmination regarding the nature of the continuous cont	Mine Employee  perience with Contractor  fears 0 Weeks 0 Days  incident or conclusions regarding the  33. Event Number
Selvin M C  24. Mining Experience a) Total Experience 5 Years 0 Weeks 0 Days  25. Autopsy Performed No  26. Mine Telephone No. (401) 943-7100  27. Description of Accident (included A miner was fatally injured when the information provided in this cause of the accident.  28. Equipment Manufacturer Not listed Fisher Industries  30. District M2000 - Warrendale District  34. Accident Investigator First Name Arthur  35. MSHA Person Notified First Name	b) Experience at the Mine 5 Years 0 Weeks 0 Days  If Yes, Location  de equipment involved, the exact leads to be entered an air classifier and was notice is based on preliminary data Communication.  MI Last Name D Wall  MI Last Name	c) Experience at the Activity at the 5 Years 0 Weeks 0 Days  cocation in the mine, and status and engulfed by material.  DNLY and does not represent final determined at 13FT Air Seperator  32. Field Office M2861 - Portsmouth NH Field 0	ge from air classifier.  Time of the Accident d) Ex 0 Y  recovery operations)  rmination regarding the nature of the continuous cont	Mine Employee  perience with Contractor  fears 0 Weeks 0 Days  incident or conclusions regarding the  33. Event Number
Selvin M C  24. Mining Experience a) Total Experience 5 Years 0 Weeks 0 Days  25. Autopsy Performed No  26. Mine Telephone No. (401) 943-7100  27. Description of Accident (includent A miner was fatally injured when the information provided in this cause of the accident.  28. Equipment Manufacturer Not listed Fisher Industries  30. District M2000 - Warrendale District  34. Accident Investigator First Name Arthur  35. MSHA Person Notified First Name Andrew	b) Experience at the Mine 5 Years 0 Weeks 0 Days  If Yes, Location  de equipment involved, the exact In the entered an air classifier and was notice is based on preliminary data Company Miles Compan	c) Experience at the Activity at the 5 Years 0 Weeks 0 Days  cocation in the mine, and status and engulfed by material.  DNLY and does not represent final determined at 13FT Air Seperator  32. Field Office M2861 - Portsmouth NH Field 0	ge from air classifier.  Time of the Accident d) Ex 0 Y  recovery operations)  rmination regarding the nature of the continuous cont	Mine Employee  perience with Contractor  fears 0 Weeks 0 Days  incident or conclusions regarding the  33. Event Number

38. Reason for Amendment