

# Preliminary Report of Accident

U.S. Department of Labor  
Mine Safety and Health Administration



PR001 09/16/2022

<b>1. Accident Type</b> F - Fatal Injury		<b>2. Accident Classification</b> 21 - Other Accident Drowning		<b>3. Date/Time of Accident</b> 09/09/2022 6:00 PM		<b>4. Date/Time of Death</b> 09/09/2022 6:00 PM		<b>5. Fatal Case No</b> FAI-6932404-1	
<b>6. Mine Information</b>									
a) Mining Company Name:		Barry Industrial Sand, Inc							
b) Mine Name:		Barry Industrial Sand, Inc.							
c) Parent of Mining Company:		Ivan D Barry							
<b>7. Mine Location Information</b>						<b>8. Mine ID Number</b>		<b>9. Union</b>	
a) City VIDOR		b) County Orange		c) State TX		41-02392			
<b>10. Primary Mineral Mined</b> Construction Sand & Gravel Mining, N.E.C.				<b>11. Number of Employees</b>			<b>d) Mill/Prep Plant</b>		<b>e) Other</b>
				a) Total 3	b) Underground	c) Open Pit/Quarry			3
<b>12. Contractor Name</b>						<b>13. Contractor Union</b>		<b>14. Contractor ID Number</b>	
<b>15. Contractor Address</b>									
a) City		b) County			c) State		d) Zip Code		
<b>16. Number of Contractor Employees</b>									
a) Total		b) Underground			c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other
<b>17. Number of Persons in Mine at Time of Accident</b>					<b>18. Number of Persons Unaccounted for</b>				
a) Mine Employees 2		b) Contractor Employees			a) Mine Employees 0		b) Contractor Employees		
<b>19. Accident Location</b> 06 - Dredge Mining								<b>20. Mining Height</b>	
								Feet	Inches
<b>21. Nonfatal Injuries</b>		<b>22. Fatal Injuries</b> 1							
<b>23. Victims Information</b>									
Elisha McMahon									
a) First Name	a) MI	a) Last Name		b) Age	c) Regular Job Title		d) Activity at Time of Accident		Employee
Elisha		McMahon		62	Dredge operator		Dredging		Mine Employee
<b>24. Mining Experience</b>									
a) Total Experience		b) Experience at the Mine			c) Experience at the Activity at the Time of the Accident			d) Experience with Contractor	
30 Years Weeks Days		30 Years Weeks Days			30 Years Weeks Days			Years Weeks Days	
<b>25. Autopsy Performed</b>									
Yes		If Yes, Location							
<b>26. Mine Telephone No.</b> (409) 769-0086									
<b>27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)</b> A dredge operator was found drowned in the dredge pond.  <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>									
<b>28. Equipment Manufacturer</b> Not listed Shop made dredge					<b>29. Model</b> NA				
<b>30. District</b> M5000 - Dallas District					<b>32. Field Office</b> M5651 - Broussard LA Field Office			<b>33. Event Number</b> 6932404	
<b>34. Accident Investigator</b>									
First Name		MI	Last Name						
Steven		W.	Oates						
<b>35. MSHA Person Notified</b>									
First Name		MI	Last Name			Date/Time Notified			
Wesley			HackWorth			09/10/2022 4:16 PM			
<b>36. Type of Report</b> Initial		<b>37. Name of Preparer</b>			<b>Date Prepared</b>				
		Full Name			09/10/2022				
		Steven W. Oates							
<b>38. Reason for Amendment</b>									