

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



PR001 01/20/2023

1. Accident Type F - Fatal Injury		2. Accident Classification 12 - Powered Haulage		3. Date/Time of Accident 01/17/2023 2:51 AM		4. Date/Time of Death 01/18/2023 3:31 AM		5. Fatal Case No FAI-6872501-1		
6. Mine Information										
a) Mining Company Name:		Calportland								
b) Mine Name:		Mojave Plant & Quarry								
c) Parent of Mining Company:		Taiheiyo Cement Corp								
7. Mine Location Information				8. Mine ID Number		9. Union				
a) City Mojave		b) County Kern		c) State CA		04-00036		No		
10. Primary Mineral Mined Hydraulic Cement				11. Number of Employees		d) Mill/Prep Plant		e) Other		
				a) Total 150		b) Underground		c) Open Pit/Quarry 23		
						69		58		
12. Contractor Name						13. Contractor Union		14. Contractor ID Number		
15. Contractor Address										
a) City		b) County			c) State			d) Zip Code		
16. Number of Contractor Employees										
a) Total		b) Underground			c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other	
17. Number of Persons in Mine at Time of Accident					18. Number of Persons Unaccounted for					
a) Mine Employees 7		b) Contractor Employees			a) Mine Employees 0		b) Contractor Employees			
19. Accident Location 00 - Other Mine Access Road								20. Mining Height 30 Feet Inches		
21. Nonfatal Injuries		22. Fatal Injuries 1								
23. Victims Information										
Kenneth M Colindres										
a) First Name Kenneth		a) MI M	a) Last Name Colindres		b) Age 47	c) Regular Job Title Weigh Master		d) Activity at Time of Accident Driving to work		Employee Mine Employee
24. Mining Experience										
a) Total Experience 19 Years 16 Weeks 0 Days			b) Experience at the Mine 19 Years 16 Weeks 0 Days			c) Experience at the Activity at the Time of the Accident 19 Years 16 Weeks 0 Days		d) Experience with Contractor 0 Years 0 Weeks 0 Days		
25. Autopsy Performed No		If Yes, Location								
26. Mine Telephone No. (661) 823-3734										
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) A miner was fatally injured when his personal vehicle collided with a customer truck while both vehicles were traveling in opposite directions on an icy mine access road. <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>										
28. Equipment Manufacturer Toyota					29. Model Echo					
30. District M7000 - Vacaville District					32. Field Office M7831 - San Bernardino CA Field Office			33. Event Number 6872501		
34. Accident Investigator										
First Name Kimberly		MI A	Last Name Hakala							
35. MSHA Person Notified										
First Name Miles		MI	Last Name Frandsen			Date/Time Notified 01/17/2023 3:24 AM				
36. Type of Report Initial		37. Name of Preparer			Date Prepared					
		Full Name James Fitch			01/17/2023					
38. Reason for Amendment										