


Fatality Alert

MINE FATALITY – On January 23, 2023, a utility management miner died, and another miner was seriously injured, while removing unused waterline pipe suspended from a mine roof. The two miners were using hand tools to remove a pipe fitting when the waterline pipe suddenly came apart, striking the victim.



Best Practices

Operators should:

- Release stored energy and pressure from pipes (block and bleed) before breaking a pipe connection.
- Lock out, tag out, and block equipment from movement before performing maintenance or repairs.
- Train miners in the safe performance of their tasks.

This is the third fatality reported in 2023, and the second classified as “Machinery”

The information provided in this notice is based on preliminary information only and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the fatality.

Report accidents and hazardous conditions: 1-800-746-1553

[msha.gov](https://www.msha.gov) | askmsha@dol.gov | [@MSHA_DOL](https://twitter.com/MSHA_DOL)