

## Fatality Alert

MINE FATALITY – On March 18, 2023, a miner died when the mine roof collapsed during the installation of standing roof support (crib) as part of the longwall recovery cycle. The accident occurred in an area adjacent to a longwall shield.



### Best Practices

- Follow the approved Roof Control Plan.
- Design, install, and maintain roof support where miners work or travel.
- Never travel under unsupported roof.
- Conduct a visual examination of the roof, face, and ribs immediately before starting work in an area.
- Be alert to changing roof conditions, especially during longwall recovery.

This is the 13th fatality reported in 2023, and the first classified as “Fall of Roof or Back.”

---

The information provided in this notice is based on preliminary information only and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the fatality.

**Report accidents and hazardous conditions: 1-800-746-1553**

[msha.gov](https://www.msha.gov) | [askmsha@dol.gov](mailto:askmsha@dol.gov) | [@MSHA\\_DOL](https://twitter.com/MSHA_DOL)