## **Preliminary Report of Accident**



## PR001 10/04/2024

1. Accident Type F - Fatal Injury	2. Accident Classification 07 - Fall of Roof or Back	3. Date/Time of 09/25/2024 12		4. Date/Time of Death 09/25/2024 12:10 AM		5. Fatal Case No FAI-6920843-1	
6. Mine Information a) Mining Company Name: b) Mine Name: c) Parent of Mining Company:	Crimson Oak Grove Reso Oak Grove Mine Alabama Kanu Holdings L						
7. Mine Location Information a) City ADGER	<b>b) County</b> Jefferson	c) State AL	8. Mine ID Num 01-00851	9. Unic Yes			
<b>10. Primary Mineral Mined</b> Bituminous Coal Underground M	11. Number of B a) Total 500	Employees b) Undergroun 374	c) Open Pit/Quarry		d) Mill/Prep Plant	<b>e) Other</b> 126	
12. Contractor Name				13. Contractor Union		14. Contractor ID Nu	mber
15. Contractor Address a) City	b) County	c) State		d) Zip Code			
16. Number of Contractor Employees a) Total b) Underground c) Open Pit/Quarry d) Mill/Prep Plant e) Other							
17. Number of Persons in Mine at Time of Accident 18. Number of Persons Unaccounted for   a) Mine Employees b) Contractor Employees   108 a) Mine Employees   b) Contractor Employees b) Contractor Employees							
<b>19. Accident Location</b> 07 - Advance Mining		1				20. Mining Height 7 Feet 0 Inches	
21. Nonfatal Injuries	22. Fatal Injuries						
23. Victims Information	I						
Jose A Lara							
a) First Name a) Jose	) <b>MI a) Last Name</b> A Lara	52 Co	<b>gular Job Title</b> ontinuous Miner perator	d) Activity at Time of Acc Hanging Tubing	cident	Employee Mine Employee	
24. Mining Experience a) Total Experience 16 Years 2 Weeks 0 Days	b) Experience at the Mine 3 Years 4 Weeks 2 Days	<b>c) Experience at t</b> 2 Years 5 Week		Time of the Accident		erience with Contracto rs Weeks Days	r
25. Autopsy Performed No	If Yes, Location						
<b>26. Mine Telephone No.</b> (205) 436-7100							
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) The victim was hanging ventilation tubing in the Number 3 entry, 60 feet inby crosscut 12 on the 7 South section, when a rock fell from the roof and struck him.							
The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding thecause of the accident.							
28. Equipment Manufacturer		29. Model					
<b>30. District</b> M3000 - Birmingham District		32. Field Office M3671 - Birn	ningham AL Field C	Office (B)		<b>33. Event Number</b> 6920843	
34. Accident Investigator First Name Thomas	MI Last Name J O'Donnell,						
35. MSHA Person Notified First Name Richard	MI Last Name Braem	9	Date/Time Not 09/25/2024 12:		_		
36. Type of Report Initial	<b>37. Name of Preparer</b> Full Name Thomas J O'Donnell, Jr.	<b>Date F</b> 09/25/	Prepared 2024				
38. Reason for Amendment			·				