

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



PR001 03/03/2025

| | | | | | | | | | |
|---|--|---|-------------------------------------|--|---|--|---|--|--|
| 1. Accident Type F - Fatal Injury | | 2. Accident Classification 12 - Powered Haulage | | 3. Date/Time of Accident 02/22/2025 2:00 AM | | 4. Date/Time of Death 02/22/2025 2:00 AM | | 5. Fatal Case No FAI-F00258A-1 | |
| 6. Mine Information | | | | | | | | | |
| a) Mining Company Name: | | GCC Dacotah Inc | | | | | | | |
| b) Mine Name: | | GCC Dacotah Inc | | | | | | | |
| c) Parent of Mining Company: | | GCC SAB de CV | | | | | | | |
| 7. Mine Location Information | | | | 8. Mine ID Number | | 9. Union | | | |
| a) City Rapid City | | b) County Pennington | | c) State SD | | 39-00022 | | Yes | |
| 10. Primary Mineral Mined Hydraulic Cement | | | | 11. Number of Employees | | | | | |
| | | | | a) Total 136 | | b) Underground | | c) Open Pit/Quarry 17 | |
| | | | | | | d) Mill/Prep Plant 99 | | e) Other 20 | |
| 12. Contractor Name Elite Refractory, LLC | | | | | | 13. Contractor Union | | 14. Contractor ID Number B8225 | |
| 15. Contractor Address | | | | | | | | | |
| a) City Waxahachie | | b) County Ellis | | c) State TX | | d) Zip Code 75165 | | | |
| 16. Number of Contractor Employees | | | | | | | | | |
| a) Total 5 | | b) Underground | | c) Open Pit/Quarry | | d) Mill/Prep Plant 5 | | e) Other | |
| 17. Number of Persons in Mine at Time of Accident | | | | | | | | | |
| a) Mine Employees 9 | | b) Contractor Employees 2 | | 18. Number of Persons Unaccounted for | | | | | |
| | | | | a) Mine Employees 0 | | b) Contractor Employees 0 | | | |
| 19. Accident Location 30 - Mill/Prep Plant | | | | | | | | 20. Mining Height Feet Inches | |
| 21. Nonfatal Injuries 0 | | 22. Fatal Injuries 1 | | | | | | | |
| 23. Victims Information | | | | | | | | | |
| Angel Gustabo-Perez-Perez | | | | | | | | | |
| a) First Name Angel | | a) MI | a) Last Name Gustabo-Perez-Perez | | b) Age 28 | c) Regular Job Title Brick Mason | | d) Activity at Time of Accident Brick Mason | |
| Employee Contractor Employee | | | | | | | | | |
| 24. Mining Experience | | | | | | | | | |
| a) Total Experience 6 Years 0 Weeks 0 Days | | b) Experience at the Mine 0 Years 0 Weeks 1 Days | | c) Experience at the Activity at the Time of the Accident 6 Years 15 Weeks 3 Days | | | d) Experience with Contractor 0 Years 15 Weeks 3 | | |
| 25. Autopsy Performed No | | | | | | | | | |
| If Yes, Location | | | | | | | | | |
| 26. Mine Telephone No. (605) 721-7100 | | | | | | | | | |
| 27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) A contractor died after the bridge providing access into a kiln collapsed, and the skid steer loader he was operating fell into the clinker chute. <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i> | | | | | | | | | |
| 28. Equipment Manufacturer Kubota | | | | | 29. Model SVL75 | | | | |
| 30. District M6000 - Denver District | | | | | 32. Field Office M6621 - Rapid City SD Field Office | | | 33. Event Number F00258A | |
| 34. Accident Investigator | | | | | | | | | |
| First Name Lee | | MI A. | Last Name Hughes | | | | | | |
| 35. MSHA Person Notified | | | | | | | | | |
| First Name Lee | | MI A | Last Name Hughes | | | Date/Time Notified 02/22/2025 3:34 AM | | | |
| 36. Type of Report Initial | | 37. Name of Preparer | | | Date Prepared | | | | |
| | | Full Name Lee A. Hughes | | | 02/24/2025 | | | | |
| 38. Reason for Amendment | | | | | | | | | |