

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



PR001 01/13/2025

1. Accident Type F - Fatal Injury		2. Accident Classification 05 - Falling, Rolling or Sliding Rock /Material		3. Date/Time of Accident 01/03/2025 6:20 PM		4. Date/Time of Death 01/03/2025 6:20 PM		5. Fatal Case No FAI-6934070-1																																																		
6. Mine Information a) Mining Company Name: WES AGG, LLC b) Mine Name: BORGER PIT c) Parent of Mining Company: JW Thomas et al																																																										
7. Mine Location Information a) City: Borger b) County: Hutchinson c) State: TX				8. Mine ID Number 41-05687		9. Union																																																				
10. Primary Mineral Mined Construction Sand & Gravel Mining, N.E.C.				11. Number of Employees a) Total: 7 b) Underground: 7 c) Open Pit/Quarry: 7 d) Mill/Prep Plant: 7 e) Other: 7																																																						
12. Contractor Name						13. Contractor Union		14. Contractor ID Number																																																		
15. Contractor Address a) City: b) County: c) State: d) Zip Code:																																																										
16. Number of Contractor Employees a) Total: b) Underground: c) Open Pit/Quarry: d) Mill/Prep Plant: e) Other:																																																										
17. Number of Persons in Mine at Time of Accident a) Mine Employees: 7 b) Contractor Employees:				18. Number of Persons Unaccounted for a) Mine Employees: 0 b) Contractor Employees:																																																						
19. Accident Location 03 - Open Pit								20. Mining Height Feet Inches:																																																		
21. Nonfatal Injuries		22. Fatal Injuries 1																																																								
23. Victims Information																																																										
<table border="1"> <thead> <tr> <th colspan="7">Segundo Bosquez</th> </tr> <tr> <th>a) First Name</th> <th>a) MI</th> <th>a) Last Name</th> <th>b) Age</th> <th>c) Regular Job Title</th> <th>d) Activity at Time of Accident</th> <th>Employee</th> </tr> </thead> <tbody> <tr> <td>Segundo</td> <td></td> <td>Bosquez</td> <td>44</td> <td>Haul Truck Operator</td> <td>Labor</td> <td>Mine Employee</td> </tr> <tr> <td colspan="7">24. Mining Experience</td> </tr> <tr> <td colspan="2">a) Total Experience Years 16 Weeks 4 Days</td> <td colspan="2">b) Experience at the Mine Years 16 Weeks 4 Days</td> <td colspan="2">c) Experience at the Activity at the Time of the Accident Years 16 Weeks 4 Days</td> <td>d) Experience with Contractor Years Weeks</td> </tr> <tr> <td colspan="7">25. Autopsy Performed Yes</td> </tr> <tr> <td colspan="7">If Yes, Location South Plains Forensics, Lubbock Texas</td> </tr> </tbody> </table>										Segundo Bosquez							a) First Name	a) MI	a) Last Name	b) Age	c) Regular Job Title	d) Activity at Time of Accident	Employee	Segundo		Bosquez	44	Haul Truck Operator	Labor	Mine Employee	24. Mining Experience							a) Total Experience Years 16 Weeks 4 Days		b) Experience at the Mine Years 16 Weeks 4 Days		c) Experience at the Activity at the Time of the Accident Years 16 Weeks 4 Days		d) Experience with Contractor Years Weeks	25. Autopsy Performed Yes							If Yes, Location South Plains Forensics, Lubbock Texas						
Segundo Bosquez																																																										
a) First Name	a) MI	a) Last Name	b) Age	c) Regular Job Title	d) Activity at Time of Accident	Employee																																																				
Segundo		Bosquez	44	Haul Truck Operator	Labor	Mine Employee																																																				
24. Mining Experience																																																										
a) Total Experience Years 16 Weeks 4 Days		b) Experience at the Mine Years 16 Weeks 4 Days		c) Experience at the Activity at the Time of the Accident Years 16 Weeks 4 Days		d) Experience with Contractor Years Weeks																																																				
25. Autopsy Performed Yes																																																										
If Yes, Location South Plains Forensics, Lubbock Texas																																																										
26. Mine Telephone No. (806) 678-0862																																																										
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) A miner died after an excavated trench collapsed and engulfed him. <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>																																																										
28. Equipment Manufacturer				29. Model																																																						
30. District M5000 - Dallas District				32. Field Office M5671 - Dallas TX Field Office				33. Event Number 6934070																																																		
34. Accident Investigator First Name: Neal MI: Last Name: Davis																																																										
35. MSHA Person Notified First Name: Ronnie MI: G Last Name: Free Date/Time Notified: 01/03/2025 6:39 PM																																																										
36. Type of Report Initial		37. Name of Preparer Full Name: Neal Davis Date Prepared: 01/03/2025																																																								
38. Reason for Amendment																																																										