

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



PR001 03/27/2026

1. Accident Type F - Fatal Injury		2. Accident Classification 17 - Machinery		3. Date/Time of Accident 03/12/2026 5:13 AM		4. Date/Time of Death 03/12/2026 05:13 AM		5. Fatal Case No FAI-F00B1D6-1																													
6. Mine Information																																					
a) Mining Company Name:		Kennecott Utah Copper LLC																																			
b) Mine Name:		Kennecott Keystone Underground																																			
c) Parent of Mining Company:		Rio Tinto Group																																			
7. Mine Location Information			8. Mine ID Number			9. Union																															
a) City South Jordan		b) County Salt Lake		c) State UT	42-01392			No																													
10. Primary Mineral Mined Copper Ore Mining, N.E.C.				11. Number of Employees		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other																											
a) Total 82				b) Underground 0		0		0		82																											
12. Contractor Name Redpath USA Corporation					13. Contractor Union No			14. Contractor ID Number R83																													
15. Contractor Address				b) County		c) State		d) Zip Code																													
a) City Sparks		Washoe		NV		89431																															
16. Number of Contractor Employees																																					
a) Total 237		b) Underground 189			c) Open Pit/Quarry 0		d) Mill/Prep Plant 0		e) Other 48																												
17. Number of Persons in Mine at Time of Accident				18. Number of Persons Unaccounted for																																	
a) Mine Employees 18		b) Contractor Employees		a) Mine Employees 0		b) Contractor Employees 0																															
19. Accident Location 02 - Surface at Underground								20. Mining Height Feet Inches																													
21. Nonfatal Injuries 0		22. Fatal Injuries 1																																			
23. Victims Information																																					
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">a) First Name Brian</td> <td style="width: 5%;">a) MI R</td> <td style="width: 20%;">a) Last Name Cameli</td> <td style="width: 5%;">b) Age 37</td> <td style="width: 20%;">c) Regular Job Title Mechanic</td> <td style="width: 20%;">d) Activity at Time of Accident Mechanic</td> <td style="width: 15%;">Employee Contractor Employee</td> </tr> <tr> <td colspan="7">24. Mining Experience</td> </tr> <tr> <td colspan="2">a) Total Experience 5 Years 5 Weeks 0 Days</td> <td colspan="2">b) Experience at the Mine 0 Years 21 Weeks 3 Days</td> <td colspan="2">c) Experience at the Activity at the Time of the Accident 5 Years 5 Weeks 0 Days</td> <td colspan="1">d) Experience with Contractor 1 Years 43 Weeks 0</td> </tr> <tr> <td colspan="2">25. Autopsy Performed Yes</td> <td colspan="5">If Yes, Location Salt Lake City</td> </tr> </table>										a) First Name Brian	a) MI R	a) Last Name Cameli	b) Age 37	c) Regular Job Title Mechanic	d) Activity at Time of Accident Mechanic	Employee Contractor Employee	24. Mining Experience							a) Total Experience 5 Years 5 Weeks 0 Days		b) Experience at the Mine 0 Years 21 Weeks 3 Days		c) Experience at the Activity at the Time of the Accident 5 Years 5 Weeks 0 Days		d) Experience with Contractor 1 Years 43 Weeks 0	25. Autopsy Performed Yes		If Yes, Location Salt Lake City				
a) First Name Brian	a) MI R	a) Last Name Cameli	b) Age 37	c) Regular Job Title Mechanic	d) Activity at Time of Accident Mechanic	Employee Contractor Employee																															
24. Mining Experience																																					
a) Total Experience 5 Years 5 Weeks 0 Days		b) Experience at the Mine 0 Years 21 Weeks 3 Days		c) Experience at the Activity at the Time of the Accident 5 Years 5 Weeks 0 Days		d) Experience with Contractor 1 Years 43 Weeks 0																															
25. Autopsy Performed Yes		If Yes, Location Salt Lake City																																			
26. Mine Telephone No. (801) 204-2000																																					
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) A contractor died on the surface of an underground mine after the boom of a drill mast collapsed and struck him. <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>																																					
28. Equipment Manufacturer Not listed Sandvik				29. Model DD422i																																	
30. District M6000 - Denver District				32. Field Office M6851 - Salt Lake City UT Field Office				33. Event Number F00B1D6																													
34. Accident Investigator																																					
First Name Lee		MI		Last Name Hughes																																	
35. MSHA Person Notified																																					
First Name Steven		MI		Last Name Polgar		Date/Time Notified 03/12/2026 5:45 AM																															
36. Type of Report Initial		37. Name of Preparer Full Name Lee Hughes			Date Prepared 03/20/2026																																
38. Reason for Amendment																																					