

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



PR001 04/02/2026

1. Accident Type F - Fatal Injury		2. Accident Classification 18 - Slip or Fall of Person		3. Date/Time of Accident 03/28/2026 9:00 AM		4. Date/Time of Death 03/28/2026 09:15 AM		5. Fatal Case No FAI-F0370F9-1	
6. Mine Information									
a) Mining Company Name:		Alpine Silica, LLC							
b) Mine Name:		Alpine Silica-San Antonio							
c) Parent of Mining Company:		Pro Frac Holding Corp							
7. Mine Location Information				8. Mine ID Number		9. Union			
a) City San Antonio		b) County Bexar		c) State TX		41-05426			
10. Primary Mineral Mined				11. Number of Employees		c) Open Pit/Quarry		d) Mill/Prep Plant	
				a) Total 55		b) Underground		55	
e) Other									
12. Contractor Name Mike Morgan Industrial, LLC						13. Contractor Union		14. Contractor ID Number B0425	
15. Contractor Address				b) County		c) State		d) Zip Code	
a) City Chelsea		Shelby		AL		35043			
16. Number of Contractor Employees									
a) Total 4		b) Underground			c) Open Pit/Quarry			d) Mill/Prep Plant	
								e) Other 4	
17. Number of Persons in Mine at Time of Accident				18. Number of Persons Unaccounted for					
a) Mine Employees 42		b) Contractor Employees 4		a) Mine Employees		b) Contractor Employees			
19. Accident Location 30 - Mill/Prep Plant								20. Mining Height Feet Inches	
21. Nonfatal Injuries		22. Fatal Injuries 1							
23. Victims Information									
Carlos Lopez									
a) First Name Carlos		a) MI P	a) Last Name Lopez		b) Age 19	c) Regular Job Title Welder/Ironworker		d) Activity at Time of Accident Repairing damaged metal roof	
Employee Contractor Employee									
24. Mining Experience									
a) Total Experience 1 Years 36 Weeks 4 Days		b) Experience at the Mine 0 Years 0 Weeks 4 Days			c) Experience at the Activity at the Time of the Accident 1 Years 36 Weeks 4 Days			d) Experience with Contractor 0 Years 32 Weeks 4	
25. Autopsy Performed Yes									
		If Yes, Location							
26. Mine Telephone No. (325) 456-2233									
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) A contractor died after falling approximately 37 feet through an un-secured roof panel of the roof of the shaker screen deck building while conducting roof repairs. <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>									
28. Equipment Manufacturer					29. Model				
30. District M5000 - Dallas District					32. Field Office M5611 - San Antonio TX Field Office			33. Event Number F0370F9	
34. Accident Investigator				MI		Last Name			
First Name Gregory		P		Sensibaugh					
35. MSHA Person Notified				MI		Last Name		Date/Time Notified	
First Name Ronnie		Free		03/28/2026 10:04 AM					
36. Type of Report Initial		37. Name of Preparer			Date Prepared				
		Full Name Gregory P Sensibaugh			03/28/2026				
38. Reason for Amendment									