Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration

PR001 11/04/2026

1. Accident Type	2. Accident Classification	3. Date/Time of Accident	4. Date/Time of Death	5. Fatal Case No
F - Fatal Injury	12 - Powered Haulage	10/23/2026 4:01 PM	10/23/2026 04:01 PM	FAI-F04AEB6-1

6. Mine Information
- **a) Mining Company Name:** Boughton Materials of Illinois, LLC
- **b) Mine Name:** Pit #1
- **c) Parent of Mining Company:** Jonathon Bradley et al

7. Mine Location Information			8. Mine ID Number	9. Union
a) City	b) County	c) State		
PLAINFIELD	Will	IL	11-02033	Yes

10. Primary Mineral Mined	11. Number of Employees				
	a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
Crushed & Broken Limestone Mining, N.E.C.	15		14		1

12. Contractor Name	13. Contractor Union	14. Contractor ID Number

15. Contractor Address			
a) City	b) County	c) State	d) Zip Code

16. Number of Contractor Employees				
a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other

17. Number of Persons in Mine at Time of Accident		18. Number of Persons Unaccounted for	
a) Mine Employees	b) Contractor Employees	a) Mine Employees	b) Contractor Employees
40		0	

19. Accident Location	20. Mining Height
03 - Open Pit	130 Feet 0 Inches

21. Nonfatal Injuries	22. Fatal Injuries
	1

23. Victims Information

David Carpenter

a) First Name	a) MI	a) Last Name	b) Age	c) Regular Job Title	d) Activity at Time of Accident	Employee
David		Carpenter	60	Haul Truck Driver	Hauling/Dumping Overburden	Mine Employee

24. Mining Experience

a) Total Experience	b) Experience at the Mine	c) Experience at the Activity at the Time of the Accident	d) Experience with Contractor
1 Years 9 Weeks 5 Days	1 Years 9 Weeks 5 Days	1 Years 9 Weeks 5 Days	0 Years 0 Weeks 0

25. Autopsy Performed	If Yes, Location
Yes	Will County Coroner 16857 W Laraway Rd Joliet Il

26. Mine Telephone No.
(630) 904-1806

27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)
A miner died after the haul truck he was operating backed over the edge of a highwall and fell 155 feet to the ground below.

The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding thecause of the accident.

28. Equipment Manufacturer	29. Model
Caterpillar	777D

30. District	32. Field Office	33. Event Number
M4000 - Duluth District		F04AEB6

34. Accident Investigator

First Name	MI	Last Name
Timothy	J	McPherson

35. MSHA Person Notified

First Name	MI	Last Name	Date/Time Notified
Elwood		Burriss	10/23/2026 5:17 PM

36. Type of Report	37. Name of Preparer	
	Full Name	Date Prepared
Initial	Timothy J McPherson	10/23/2026

38. Reason for Amendment