Preliminary Report of Accident



PR001 01/11/2023

1. Accident Type F - Fatal Injury	0. A solution to Ole solf is still an			
	2. Accident Classification 17 - Machinery	3. Date/Time of Accident 01/04/2023 3:07 PM	4. Date/Time of Death 01/04/2023 5:30 PM	5. Fatal Case No FAI-7037241-1
6. Mine Information a) Mining Company Name: b) Mine Name: c) Parent of Mining Company:	Vulcan Construction Materials, Ll Sevierville Quarry Vulcan Materials Company	LC		
7. Mine Location Information a) City Sevierville	b) County Sevier	c) State TN	8. Mine ID Number 40-00115	9. Union No
10. Primary Mineral Mined Crushed & Broken Limestone M	ining, N.E.C.	11. Number of Employees a) Total b) Under 17	ground c) Open Pit/Quarry 8	d) Mill/Prep Plant e) Other 4 5
12. Contractor Name			13. Contractor Union	14. Contractor ID Number
15. Contractor Address		-) 04-4-	d) Zin Onde	1
a) City	b) County	c) State	d) Zip Code	
16. Number of Contractor Employ a) Total	ees b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
17. Number of Persons in Mine at Time of Accident 18. Number of Persons Unaccounted for a) Mine Employees b) Contractor Employees a) Mine Employees b) Contractor Employees 15 0				
19. Accident Location 30 - Mill/Prep Plant				20. Mining Height 0 Feet 0 Inches
21. Nonfatal Injuries 0	22. Fatal Injuries			1
23. Victims Information				
John Ogle				
	,	r Job Title d) Activity at Time o Il Labor Maintenance	fAccident	Employee Mine Employee
24. Mining Experience			e Time of the Accident d) Ex	
a) Total Experience 1 Years 50 Weeks 6 Days	b) Experience at the Mine 1 Years 50 Weeks 6 Days	c) Experience at the Activity at th 1 Years 50 Weeks 6 Days		perience with Contractor
1 Years 50 Weeks 6 Days	1 Years 50 Weeks 6 Days			•
1 Years 50 Weeks 6 Days 25. Autopsy Performed	1 Years 50 Weeks 6 Days If Yes, Location	1 Years 50 Weeks 6 Days		•
1 Years 50 Weeks 6 Days	1 Years 50 Weeks 6 Days	1 Years 50 Weeks 6 Days		-
1 Years 50 Weeks 6 Days 25. Autopsy Performed	1 Years 50 Weeks 6 Days If Yes, Location	1 Years 50 Weeks 6 Days		-
1 Years 50 Weeks 6 Days 25. Autopsy Performed Yes 26. Mine Telephone No. (865) 453-0417 27. Description of Accident (inclue A miner was fatally injured while pinning the miner against the cru	1 Years 50 Weeks 6 Days If Yes, Location Regional Forensics Center in Kr de equipment involved, the exact lo being positioned between the pitmar usher housing.	1 Years 50 Weeks 6 Days	0 Y ecovery operations) a jaw crusher to remove a toggle bear	ears 0 Weeks 0 Days
1 Years 50 Weeks 6 Days 25. Autopsy Performed Yes 26. Mine Telephone No. (865) 453-0417 27. Description of Accident (included A miner was fatally injured while pinning the miner against the cruter of the miner against the cruter of the accident.	1 Years 50 Weeks 6 Days If Yes, Location Regional Forensics Center in Kr de equipment involved, the exact lo being positioned between the pitmar usher housing.	1 Years 50 Weeks 6 Days noxville, TN Docation in the mine, and status and r n assembly and the crusher housing of DNLY and does not represent final dete	0 Y ecovery operations) a jaw crusher to remove a toggle bear	ears 0 Weeks 0 Days
1 Years 50 Weeks 6 Days 25. Autopsy Performed Yes 26. Mine Telephone No. (865) 453-0417 27. Description of Accident (include A miner was fatally injured while pinning the miner against the cru The information provided in this	1 Years 50 Weeks 6 Days If Yes, Location Regional Forensics Center in Kr de equipment involved, the exact lo being positioned between the pitmar usher housing.	1 Years 50 Weeks 6 Days noxville, TN Decation in the mine, and status and r n assembly and the crusher housing of	0 Y ecovery operations) a jaw crusher to remove a toggle bear	ears 0 Weeks 0 Days
1 Years 50 Weeks 6 Days 25. Autopsy Performed Yes 26. Mine Telephone No. (865) 453-0417 27. Description of Accident (inclue A miner was fatally injured while pinning the miner against the cru The information provided in this cause of the accident. 28. Equipment Manufacturer	1 Years 50 Weeks 6 Days If Yes, Location Regional Forensics Center in Kr de equipment involved, the exact lo being positioned between the pitmar usher housing.	1 Years 50 Weeks 6 Days noxville, TN Decation in the mine, and status and r n assembly and the crusher housing of DNLY and does not represent final deter 29. Model	ecovery operations) a jaw crusher to remove a toggle bear rmination regarding the nature of the ir	ears 0 Weeks 0 Days
1 Years 50 Weeks 6 Days 25. Autopsy Performed Yes 26. Mine Telephone No. (865) 453-0417 27. Description of Accident (inclue A miner was fatally injured while pinning the miner against the cru The information provided in this cause of the accident. 28. Equipment Manufacturer Not listed Hewitt Robins 30. District	1 Years 50 Weeks 6 Days If Yes, Location Regional Forensics Center in Kr de equipment involved, the exact lo being positioned between the pitmar usher housing.	1 Years 50 Weeks 6 Days noxville, TN Docation in the mine, and status and r n assembly and the crusher housing of DNLY and does not represent final dete 29. Model 42 X 48 Grizzly King 32. Field Office	ecovery operations) a jaw crusher to remove a toggle bear rmination regarding the nature of the ir	ears 0 Weeks 0 Days ing. The pitman assembly rotated, incident or conclusions regarding the 33. Event Number
1 Years 50 Weeks 6 Days 25. Autopsy Performed Yes 26. Mine Telephone No. (865) 453-0417 27. Description of Accident (inclue A miner was fatally injured while pinning the miner against the cru The information provided in this cause of the accident. 28. Equipment Manufacturer Not listed Hewitt Robins 30. District C0700 - Barbourville District 34. Accident Investigator First Name David 35. MSHA Person Notified First Name David	1 Years 50 Weeks 6 Days If Yes, Location Regional Forensics Center in Kr de equipment involved, the exact to being positioned between the pitmar usher housing. notice is based on preliminary data C MI Last Name A. Faulkner MI Last Name MI Last Name	1 Years 50 Weeks 6 Days noxville, TN Docation in the mine, and status and r n assembly and the crusher housing of DNLY and does not represent final dete 29. Model 42 X 48 Grizzly King 32. Field Office C0712 - Knoxville TN Field Office Date/Time No	ecovery operations) a jaw crusher to remove a toggle bear rmination regarding the nature of the ir	ears 0 Weeks 0 Days ing. The pitman assembly rotated, incident or conclusions regarding the 33. Event Number
1 Years 50 Weeks 6 Days 25. Autopsy Performed Yes 26. Mine Telephone No. (865) 453-0417 27. Description of Accident (inclue A miner was fatally injured while pinning the miner against the cru The information provided in this cause of the accident. 28. Equipment Manufacturer Not listed Hewitt Robins 30. District C0700 - Barbourville District 34. Accident Investigator First Name David 35. MSHA Person Notified	1 Years 50 Weeks 6 Days If Yes, Location Regional Forensics Center in Kr de equipment involved, the exact to being positioned between the pitmar usher housing. notice is based on preliminary data C MI Last Name A. Faulkner	1 Years 50 Weeks 6 Days noxville, TN Decation in the mine, and status and r n assembly and the crusher housing of DNLY and does not represent final dete 29. Model 42 X 48 Grizzly King 32. Field Office C0712 - Knoxville TN Field Office	ecovery operations) a jaw crusher to remove a toggle bear rmination regarding the nature of the ir	ears 0 Weeks 0 Days ing. The pitman assembly rotated, incident or conclusions regarding the 33. Event Number