

# Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Falling, Rolling or Sliding Rock /Materl		3. Date/Time of Accident 12/19/2016 04:52 AM		4. Date/Time of Death 12/19/2016 04:52 AM		5. Fatal Case No 15		
6. Mine Information :										
a) Mining Company Name Atlanta Sand and Supply Co Inc			b) Mine Name Roberta Mine			c) Parent of Mining Company Curt B Jamison				
7. Mine Location :		a) City Roberta		b) County Crawford		c) State GA		8. Mine ID Number: 09-00264		9. Union: NO
10. Primary Mineral Mined: COMMON SAND MINING			11. Number of Mine Employees:		a) Total 37	b) Underground	c) Open Pit/Quarry 5		d) Mill/Prep Plant 32	e) Other
12. Contractor Name:						13. Union		14. Contractor ID Number:		
15. Contractor Address:		a) City		b) County		c) State		d) Zip Code		
16. Number of Contractor Employees:		a) Total	b) Underground	c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other		
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 9		b) Contractor Employees: 0			a) Mine Employees: 0		b) Contractor Employees: 0			
19) Location of Accident									20. Mining Height:	
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		Feet	Inches
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility					
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1								
23. Victim Information :										
a) Name Richard C. Anderson					b) Age 62					
c) Regular Job Title: Wash Plant and Front End Loader Oper				d) Activity at Time of Accident: Loading Feed Hopper				<input checked="" type="checkbox"/> Mine Employee		
24. Experience :	Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days			
a) Total:	6	20	b) at the mine:	6	20	c) at activity (23d)	5	40	d) with Contractor	
25. Autopsy Performed: If Yes, Location YES State Crime Lab Macon						26. Mine Telephone No.: (478) 836-4275				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was a Wash Plant and Front-end Loader Operator and was using a front-end loader to load sand into the loading feed hopper. The victim apparently got off the front-end loader and appears to have been trying to retrieve two 55 gallon drum lids and entered or fell into the hopper and became engulfed in the sand.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:				29. Model:			
30. District: M3000 Southeastern		32. Field Office: Macon GA				33. Event Number: 0916658	
34. Accident Investigator: Curtis Roth			35. MSHA Person Notified: Michael Evans		Date 12/19/2016	Time 05:36 AM	
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Michael Evans				Date 12/20/2016	
38. Reason For Amendment:							