

# Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Machinery		3. Date/Time of Accident 03/06/2019 10:20 AM		4. Date/Time of Death 03/06/2019 11:32 AM		5. Fatal Case No 3			
6. Mine Information :											
a) Mining Company Name Freeport-McMoRan Tyrone Inc			b) Mine Name TYRONE MINE			c) Parent of Mining Company Freeport-McMoRan Inc					
7. Mine Location :		a) City Tyrone		b) County Grant		c) State NM		8. Mine ID Number: 29-00159		9. Union: NO	
10. Primary Mineral Mined: COPPER ORE MINING, N.E.C.			11. Number of Mine Employees:		a) Total 365	b) Underground	c) Open Pit/Quarry 144	d) Mill/Prep Plant	e) Other 221		
12. Contractor Name: Joy Global DBA Komatsu Mining Corp						13. Union NO		14. Contractor ID Number: P001			
15. Contractor Address:		a) City Mesa		b) County Maricopa		c) State AZ		d) Zip Code 85210-6105			
16. Number of Contractor Employees:		a) Total 66		b) Underground		c) Open Pit/Quarry 56		d) Mill/Prep Plant		e) Other 10	
17. Number of Persons in Mine at Time of Accident:						18. Number of Persons Unaccounted For:					
a) Mine Employees: 231		b) Contractor Employees: 64		a) Mine Employees: 0		b) Contractor Employees: 0					
19) Location of Accident									20. Mining Height:		
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)	Feet	Inches	<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility	
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1									
23. Victim Information :											
a) Name Timothy Rivers					b) Age 35						
c) Regular Job Title: Mechanic											
d) Activity at Time of Accident: Shovel undercarriage rebuild <input checked="" type="checkbox"/> Contractor Employee											
24. Experience :											
Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days					
a) Total: 35 5		b) at the mine: 3		c) at activity (23d) 35 0		d) with Contractor 35 5					
25. Autopsy Performed: If Yes, Location YES Albuquerque, NM						26. Mine Telephone No.: (575) 912-5727					

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

A contract miner was placing the last of four 500-ton hydraulic jacks in position under a 4100A shovel when the relief valve was ejected from the jack. The hydraulic jack was being pumped up to make contact with the shovel frame. The relief valve struck the victim in the lower left abdomen causing a deep laceration.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Enerpac				29. Model: 500 Ton			
30. District: M5000 South Central		32. Field Office: Albuquerque NM			33. Event Number: 6807716		
34. Accident Investigator: Lee Cruise			35. MSHA Person Notified: Mac Burriss		Date 03/06/2019	Time 10:43 AM	
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Elwood M. Burriss				Date 03/08/2019	
38. Reason For Amendment:							