

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Slip or Fall of Person		3. Date/Time of Accident 03/07/2019 03:30 AM		4. Date/Time of Death 03/07/2019 03:30 AM		5. Fatal Case No 4		
6. Mine Information :										
a) Mining Company Name CEMEX Construction Materials South, LLC			b) Mine Name Balcones Quarry			c) Parent of Mining Company Cemex S A				
7. Mine Location :		a) City New Braunfels		b) County Comal		c) State TX		8. Mine ID Number: 41-00994		9. Union: NO
10. Primary Mineral Mined: CRUSHED & BROKEN LIMESTONE M			11. Number of Mine Employees:		a) Total 86	b) Underground	c) Open Pit/Quarry 86	d) Mill/Prep Plant		e) Other
12. Contractor Name: Robben's Fabrication and Mechanical LLC						13. Union NO		14. Contractor ID Number: B6573		
15. Contractor Address:		a) City Seguin		b) County Guadalupe		c) State TX		d) Zip Code 78155		
16. Number of Contractor Employees:		a) Total 3		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant 3		e) Other
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 35		b) Contractor Employees: 3			a) Mine Employees: 0		b) Contractor Employees: 0			
19) Location of Accident									20. Mining Height:	
<input type="checkbox"/> 01-Underground	<input type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input checked="" type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		Feet Inches	
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility					
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1								
23. Victim Information :										
a) Name Jesus R. Dominguez					b) Age 46					
c) Regular Job Title: Contractor										
d) Activity at Time of Accident: Changing drive belts on Log washer <input checked="" type="checkbox"/> Contractor Employee										
24. Experience :										
Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days				
a) Total: 3		b) at the mine: 37		c) at activity (23d) 3		d) with Contractor 37				
25. Autopsy Performed: If Yes, Location						26. Mine Telephone No.: (830) 625-9186				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
A contract miner was changing drive belts on a log washer motor. The victim lost his balance and fell backwards through a narrow gap between two log washers and landed on a cable tray nine feet below.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: McLanahan			29. Model: Log washer		
30. District: M5000 South Central		32. Field Office: San Antonio TX			33. Event Number:
34. Accident Investigator: Wesley Hackworth			35. MSHA Person Notified: Brett Barrick		Date 03/07/2019
					Time 10:10 AM
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Elwood M. Burriss			Date 03/08/2019
38. Reason For Amendment:					