

Preliminary Report of Accident
PR001 05/21/2019

U.S. Department of Labor
Mine Safety and Health Administration



1. Accident Type F - Fatal Injury		2. Accident Classification 18 - Slip or Fall of Person		3. Date/Time of Accident 05/18/2019 3:37 PM		4. Date/Time of Death 05/18/2019 3:37 PM		5. Fatal Case No 8					
6. Mine Information													
a) Mining Company Name:		Rogers Group Inc.											
b) Mine Name:		West Amarillo Sand & Gravel											
c) Parent of Mining Company:		Rogers Group Inc											
7. Mine Location Information						8. Mine ID Number		9. Union					
a) City Vega		b) County Oldham		c) State TX		41-04358		No					
10. Primary Mineral Mined Construction Sand & Gravel Mining, N.E.C.				11. Number of Employees									
				a) Total 25		b) Underground		c) Open Pit/Quarry 25		d) Mill/Prep Plant		e) Other	
12. Contractor Name						13. Contractor Union		14. Contractor ID Number					
15. Contractor Address													
a) City		b) County			c) State			d) Zip Code					
16. Number of Contractor Employees													
a) Total		b) Underground			c) Open Pit/Quarry			d) Mill/Prep Plant			e) Other		
17. Number of Persons in Mine at Time of Accident					18. Number of Persons Unaccounted for								
a) Mine Employees 20		b) Contractor Employees			a) Mine Employees		b) Contractor Employees						
19. Accident Location 03 - Open Pit								20. Mining Height Feet Inches					
21. Nonfatal Injuries		22. Fatal Injuries 1											
23. Victims Information													
Richard E Ramirez													
a) First Name Richard		a) MI E	a) Last Name Ramirez		b) Age 34	c) Regular Job Title Plant Operator		d) Activity at Time of Accident Plant Operator		Employee Mine Employee			
24. Mining Experience													
a) Total Experience 8 Years 16 Weeks 0 Days		b) Experience at the Mine 0 Years 20 Weeks 0 Days			c) Experience at the Activity at the Time of the Accident 0 Years 20 Weeks 0 Days			d) Experience with Contractor 0 Years 0 Weeks 0 Days					
25. Autopsy Performed Yes		If Yes, Location South Plains Forensic, Lubbock TX											
26. Mine Telephone No. (806) 267-0218													
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) Miner was using a man lift basket to clear a cone crusher stoppage at a height of 28 feet. The miner was wearing fall protection harness and a retractable lanyard but was not secured/tied off to the man lift basket. The miner was ejected from the man lift basket to the surface below. <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>													
28. Equipment Manufacturer Not listed Snorkel					29. Model PB-60D7								
30. District M5000 - South Central District - Dallas					32. Field Office M5641 - Albuquerque NM Field Office			33. Event Number 6806769					
34. Accident Investigator													
First Name Dwight		MI	Last Name Shields										
35. MSHA Person Notified													
First Name Elwood		MI M	Last Name Burriss			Date/Time Notified 05/18/2019 4:06 PM							
36. Type of Report Initial		37. Name of Preparer			Date Prepared								
		Full Name Elwood Burriss			05/20/2019								
38. Reason for Amendment													