

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



PR001 03/06/2020

1. Accident Type F - Fatal Injury		2. Accident Classification 09 - Handling Material		3. Date/Time of Accident 02/27/2020 1:45 PM		4. Date/Time of Death 02/27/2020 1:45 PM		5. Fatal Case No 6835342-1					
6. Mine Information													
a) Mining Company Name:		Michigan Materials and Aggregates Company											
b) Mine Name:		Patterson Road											
c) Parent of Mining Company:		CRH PLC											
7. Mine Location Information					8. Mine ID Number		9. Union						
a) City Middleville		b) County Allegan		c) State MI		20-02995		No					
10. Primary Mineral Mined Construction Sand & Gravel Mining, N.E.C.				11. Number of Employees									
				a) Total 9		b) Underground		c) Open Pit/Quarry 9		d) Mill/Prep Plant 0		e) Other 0	
12. Contractor Name						13. Contractor Union		14. Contractor ID Number					
15. Contractor Address													
a) City		b) County			c) State			d) Zip Code					
16. Number of Contractor Employees													
a) Total		b) Underground			c) Open Pit/Quarry			d) Mill/Prep Plant		e) Other			
17. Number of Persons in Mine at Time of Accident					18. Number of Persons Unaccounted for								
a) Mine Employees 9		b) Contractor Employees 0			a) Mine Employees 0		b) Contractor Employees 0						
19. Accident Location 03 - Open Pit								20. Mining Height					
								Feet		Inches			
21. Nonfatal Injuries		22. Fatal Injuries 1											
23. Victims Information													
Ronald A Baughman II													
a) First Name Ronald		a) MI A	a) Last Name Baughman II		b) Age 29	c) Regular Job Title Equipment Operator		d) Activity at Time of Accident Plant Set-Up		Employee Mine Employee			
24. Mining Experience													
a) Total Experience 1 Years 49 Weeks 6 Days			b) Experience at the Mine 1 Years 49 Weeks 6 Days			c) Experience at the Activity at the Time of the Accident 1 Years 49 Weeks 6 Days			d) Experience with Contractor 0 Years 0 Weeks 0 Days				
25. Autopsy Performed Yes		If Yes, Location Allegan County											
26. Mine Telephone No. (269) 795-3500													
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) A miner was struck by a 20' x 8' x 1-inch metal plate being installed on a Feeder Hopper. <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>													
28. Equipment Manufacturer					29. Model								
30. District M4000 - North Central District - Duluth					32. Field Office M4631 - Lansing MI Field Office			33. Event Number 6835342					
34. Accident Investigator													
First Name Duane		MI L	Last Name Hongisto										
35. MSHA Person Notified													
First Name George		MI F	Last Name Schorr			Date/Time Notified 02/27/2020 1:48 PM							
36. Type of Report Initial		37. Name of Preparer			Date Prepared								
		Full Name Christopher G Veenstra			02/28/2020								
38. Reason for Amendment													