

Preliminary Report of Accident
PR001 05/21/2019

U.S. Department of Labor
Mine Safety and Health Administration



1. Accident Type F - Fatal Injury		2. Accident Classification 18 - Powered Haulage		3. Date/Time of Accident 05/18/2019 3:37 PM		4. Date/Time of Death 05/18/2019 3:37 PM		5. Fatal Case No 8						
6. Mine Information														
a) Mining Company Name:		Rogers Group Inc.												
b) Mine Name:		West Amarillo Sand & Gravel												
c) Parent of Mining Company:		Rogers Group Inc												
7. Mine Location Information						8. Mine ID Number		9. Union						
a) City Vega		b) County Oldham		c) State TX		41-04358		No						
10. Primary Mineral Mined Construction Sand & Gravel Mining, N.E.C.				11. Number of Employees										
				a) Total 25		b) Underground		c) Open Pit/Quarry 25		d) Mill/Prep Plant		e) Other		
12. Contractor Name						13. Contractor Union		14. Contractor ID Number						
15. Contractor Address														
a) City			b) County			c) State			d) Zip Code					
16. Number of Contractor Employees														
a) Total			b) Underground			c) Open Pit/Quarry			d) Mill/Prep Plant			e) Other		
17. Number of Persons in Mine at Time of Accident						18. Number of Persons Unaccounted for								
a) Mine Employees 20			b) Contractor Employees			a) Mine Employees			b) Contractor Employees					
19. Accident Location 03 - Open Pit								20. Mining Height Feet Inches						
21. Nonfatal Injuries				22. Fatal Injuries 1										
23. Victims Information														
Richard E Ramirez														
a) First Name		a) MI	a) Last Name		b) Age	c) Regular Job Title		d) Activity at Time of Accident		Employee				
Richard		E	Ramirez		34	Plant Operator		Plant Operator		Mine Employee				
24. Mining Experience														
a) Total Experience			b) Experience at the Mine			c) Experience at the Activity at the Time of the Accident			d) Experience with Contractor					
8 Years 16 Weeks 0 Days			0 Years 20 Weeks 0 Days			0 Years 20 Weeks 0 Days			0 Years 0 Weeks 0 Days					
25. Autopsy Performed		If Yes, Location												
Yes		South Plains Forensic, Lubbock TX												
26. Mine Telephone No. (806) 267-0218														
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) Miner was using a man lift basket to clear a cone crusher stoppage at a height of 28 feet. The miner was wearing fall protection harness and a retractable lanyard but was not secured/tied off to the man lift basket. The miner was ejected from the man lift basket to the surface below. <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>														
28. Equipment Manufacturer Not listed Snorkel					29. Model PB-60D7									
30. District M5000 - South Central District - Dallas					32. Field Office M5641 - Albuquerque NM Field Office			33. Event Number 6806769						
34. Accident Investigator														
First Name			MI	Last Name										
Dwight				Shields										
35. MSHA Person Notified														
First Name			MI	Last Name			Date/Time Notified							
Elwood			M	Burriss			05/18/2019 4:06 PM							
36. Type of Report Initial			37. Name of Preparer Full Name			Date Prepared								
			Elwood Burriss			05/20/2019								
38. Reason for Amendment														