

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



PR001 05/05/2020

1. Accident Type F - Fatal Injury		2. Accident Classification 09 - Handling Material		3. Date/Time of Accident 05/02/2020 9:01 AM		4. Date/Time of Death 05/02/2020 10:15 AM		5. Fatal Case No 6892148-01	
6. Mine Information									
a) Mining Company Name:		Enon Sand & Gravel LLC							
b) Mine Name:		Enon Sand & Gravel							
c) Parent of Mining Company:		Jason R Jurgensen et al							
7. Mine Location Information					8. Mine ID Number		9. Union		
a) City ENON		b) County Clark		c) State OH		33-01466		No	
10. Primary Mineral Mined Construction Sand & Gravel Mining, N.E.C.				11. Number of Employees					
				a) Total 9		b) Underground		c) Open Pit/Quarry 5	
						d) Mill/Prep Plant 3		e) Other 1	
12. Contractor Name						13. Contractor Union		14. Contractor ID Number	
15. Contractor Address									
a) City		b) County			c) State			d) Zip Code	
16. Number of Contractor Employees									
a) Total		b) Underground			c) Open Pit/Quarry			d) Mill/Prep Plant	
								e) Other	
17. Number of Persons in Mine at Time of Accident					18. Number of Persons Unaccounted for				
a) Mine Employees 4		b) Contractor Employees			a) Mine Employees 0		b) Contractor Employees		
19. Accident Location 06 - Dredge Mining								20. Mining Height	
								Feet Inches	
21. Nonfatal Injuries		22. Fatal Injuries 1							
23. Victims Information									
Rodger A. Zimmerman									
a) First Name Rodger		a) MI A.	a) Last Name Zimmerman		b) Age 56	c) Regular Job Title Pit loader operator		d) Activity at Time of Accident Clearing blockage in feed hopper	
Employee Mine Employee									
24. Mining Experience									
a) Total Experience 8 Years 4 Weeks 0 Days		b) Experience at the Mine 1 Years 12 Weeks 0 Days			c) Experience at the Activity at the Time of the Accident 1 Years 12 Weeks 0 Days			d) Experience with Contractor Years Weeks Days	
25. Autopsy Performed Yes		If Yes, Location Montgomery County, Ohio							
26. Mine Telephone No. (937) 882-6357									
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) The victim entered the feed hopper through an access hatch near the bottom of the bin in an attempt to clear a blockage. The material remaining in the hopper slid down and engulfed the miner while he was working inside. <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>									
28. Equipment Manufacturer Not listed Hartman Fabco					29. Model Feed Hopper				
30. District M2000 - Warrendale District					32. Field Office M2651 - Hebron OH Field Office			33. Event Number 6892148	
34. Accident Investigator									
First Name Rodney		MI L	Last Name Rice						
35. MSHA Person Notified									
First Name Thomas		MI E	Last Name Rasmussen			Date/Time Notified 05/02/2020 10:02 AM			
36. Type of Report Initial		37. Name of Preparer			Date Prepared				
		Full Name Thomas E Rasmussen			05/02/2020				
38. Reason for Amendment									