

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



PR001 06/04/2020

1. Accident Type F - Fatal Injury		2. Accident Classification 18 - Slip or Fall of Person		3. Date/Time of Accident 06/01/2020 1:05 PM		4. Date/Time of Death 06/01/2020 2:46 PM		5. Fatal Case No FAI-6786324-1					
6. Mine Information													
a) Mining Company Name:		Desert Aggregates											
b) Mine Name:		Plant 1											
c) Parent of Mining Company:		Gary Curtis											
7. Mine Location Information					8. Mine ID Number		9. Union						
a) City		b) County		c) State		02-03413		No					
Goodyear		Maricopa		AZ									
10. Primary Mineral Mined				11. Number of Employees									
Construction Sand & Gravel Mining, N.E.C.				a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other	
				13		3		9		1			
12. Contractor Name						13. Contractor Union		14. Contractor ID Number					
L. J. E. Trucking								C1001					
15. Contractor Address													
a) City		b) County			c) State		d) Zip Code						
Buckeye					AZ		86396						
16. Number of Contractor Employees													
a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other					
2		0		0		0		2					
17. Number of Persons in Mine at Time of Accident				18. Number of Persons Unaccounted for									
a) Mine Employees		b) Contractor Employees		a) Mine Employees		b) Contractor Employees							
13		0		0		0							
19. Accident Location								20. Mining Height					
03 - Open Pit								20 Feet Inches					
21. Nonfatal Injuries		22. Fatal Injuries											
0		1											
23. Victims Information													
Salvador Moreno													
a) First Name		a) MI	a) Last Name		b) Age	c) Regular Job Title		d) Activity at Time of Accident		Employee			
Salvador			Moreno		61	Over the Road Truck Driver		Deploying Trailer Tarp		Contractor Employee			
24. Mining Experience													
a) Total Experience		b) Experience at the Mine		c) Experience at the Activity at the Time of the Accident			d) Experience with Contractor						
0 Years 4 Weeks 0 Days		0 Years 4 Weeks 0 Days		0 Years 4 Weeks 0 Days			0 Years 4 Weeks 0 Days						
25. Autopsy Performed		If Yes, Location											
Yes		Maricopa County											
26. Mine Telephone No.													
(480) 568-7407													
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)													
The accident occurred when an over-the-road truck driver was attempting to deploy the trailer tarp on his truck. The victim fell from the trailer, striking the ground. CPR was attempted at the scene until EMS arrived. The victim was transported by EMS to local hospital where he was pronounced dead.													
<i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>													
28. Equipment Manufacturer				29. Model									
Mack				CSU613									
30. District				32. Field Office				33. Event Number					
M6000 - Denver District				M6862 - Mesa South AZ Field Office				6786324					
34. Accident Investigator													
First Name		MI		Last Name									
Clayton				Johnson									
35. MSHA Person Notified													
First Name		MI		Last Name		Date/Time Notified							
Thomas				Stefansky		06/01/2020 1:21 PM							
36. Type of Report		37. Name of Preparer											
Initial		Full Name		Date Prepared									
		Peter DeIDuca		06/03/2020									
38. Reason for Amendment													