## **Examination of Working Places**

Location: Cryptic Mine Date			<b>Date:</b> 23	ate: 23 August 2019		
Working places must be examined at least once each shift, before miners begin work in that place. Record ALL conditions found on entire shift.						
Competent Person: Joe Miner Shift: 1st				rd		
A competent person should be Task Trained to recognize hazards and conditions that are expected or known to occur in a specific work area						
Location of all areas examined: Mark 'CAN' box if "Corrective Action Needed" is found. IF conditions that may adversely affect safety or health cannot be corrected before miners are potentially exposed the miners must be promptly notified of the condition						
Working Place	CAN	Working Place		CAN		
Quarry	CAN 🗌	N. Screen Plant Lab		CAN 🗌		
Primary Crusher Plant	CAN 🗌	Maintenance Garage			CAN 🗌	
S. Screen Plant	CAN 🛛	Scale House			CAN 🗌	
S. Screen Plant Lab	CAN 🗌				CAN 🗌	
N. Screen Plant	CAN 🗌				CAN 🗌	
Location of all areas NOT Regularly Inspected - Mark 'CAN' box if "Corrective Action Needed" is found Areas Not Regularly Inspected MUST be inspected BEFORE miners begin work in that place						
Working Place	CAN	Working Place CAN				
Bone Yard	CAN 🗌	Warehouse			CAN 🗌	
	CAN 🗌				CAN 🗌	
	CAN 🗌				CAN 🗌	
	CAN 🗌				CAN 🗌	
Corrective Action Needed. Mine operators must promptly initiate corrective action of any condition that may adversely affect miners' safety and health Notified					Date Corrected	
Broken Guard on S. Screen Plant Floor #2 Head Pulley section of Conveyor A2 YES 🛛					12 June 2019	
YES 🗌						
YES 🗌						
YES 🗌						
YES 🗌						
Additional items found that do NOT adversely affect safety or health					Date Corrected	
Restock ear plugs in S. Screen Plant						

Definitions and explanations:

\*A continuing adverse condition does not need to be recorded on each shift as per MSHA guidance document (FAQ).

\*A working place would not include roads not directly involved in the mining process, administrative office buildings, parking lots, lunchrooms, toilet facilities, or inactive storage areas as per MSHA guidance documents (FAQ and Fact Sheet).

Work Place	Provide a specific definition of each Work Place		
Primary Crusher Plant & Conveyor A1	Primary crusher plant and conveyor A1 to include immediate area around and dump site.		
S. Screen Plant	S. Screen Plant Floors 1-3 and S. Screen Plant Discharge Conveyors A3, A4 & A5 including the top of Silos A, B and C		
S. Screen Plant Lab	Includes the lab and walkways leading to and from		
N. Screen Plant	N. Screen Plant Floors 1-4 and Discharge Conveyors B1, B2 & B3 including top of Silos D, E & F		
N. Screen Plant Lab	Includes the lab and walkways leading to and from		
Maintenance Garage	Maintenance Garage and surrounding access ways		
Scale House	The scale house, the bottom of all silos and scales		
Quarry	The quarry is Pit #3 on the southwest corner of the mine and includes the haulways leading to the primary crusher and the currently mined highwall on the west perimeter of the pit		

Work Place NOT Regularly Inspected	Provide a specific definition of each Work Place that is NOT regularly inspected
Bone Yard	Located behind Maintenance garage where outside storage and stare equipment if found
Warehouse	Located east of S. Screen Plant
Pump house #1	Located at Pit #2 retention pond