

## Fatality Alert

MINE FATALITY – On December 14, 2023, a contractor died while delivering parts to the mine when an all-terrain telehandler pulling cable, tipped over, striking him.



### Best Practices

- Do not exceed the load radius and load limits of lifting equipment.
- Ensure miners position themselves in a safe manner while working around equipment.
- Barricade and sign affected areas in case equipment or loads fail or tip.
- Ensure visitors entering the mine receive site specific hazard awareness training.
- Maintain good communication between co-workers.

This is the 40<sup>th</sup> fatality reported in 2023, and the 16<sup>th</sup> classified as “Machinery.”

---

The information provided in this notice is based on preliminary information only and does not represent final determinations regarding the nature of the accident or conclusions regarding the cause of the fatality.

**Report accidents and hazardous conditions: 1-800-746-1553**

[msha.gov](https://www.msha.gov) | [askmsha@dol.gov](mailto:askmsha@dol.gov) | [@MSHA\\_DOL](https://twitter.com/MSHA_DOL)