

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Falling, Rolling or Sliding Rock /Material		3. Date/Time of Accident 02/26/2016 08:35 AM		4. Date/Time of Death 02/26/2016 10:04 AM		5. Fatal Case No 1		
6. Mine Information :										
a) Mining Company Name Lonestar Prospects Ltd.			b) Mine Name Vista Sand			c) Parent of Mining Company RJS Holdings LLC; MWR Holdings LLC				
7. Mine Location :			a) City Granbury		b) County Hood		c) State TX		8. Mine ID Number: 41-04430	9. Union: NO
10. Primary Mineral Mined: CONSTRUCTION SAND & GRAVEL M			11. Number of Mine Employees:		a) Total 156	b) Underground 0	c) Open Pit/Quarry 59	d) Mill/Prep Plant 26	e) Other 71	
12. Contractor Name: Powell Transportation Company						13. Union NO		14. Contractor ID Number:		
15. Contractor Address:			a) City Columbia		b) County Marion		c) State MS		d) Zip Code 39429	
16. Number of Contractor Employees:			a) Total 4	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other 4			
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 67		b) Contractor Employees: 4			a) Mine Employees: 0		b) Contractor Employees: 0			
19. Location of Accident									20. Mining Height: Feet Inches	
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)						
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility							
21. Nonfatal Injuries: 0			22. Fatal Injuries: 1							
23. Victim Information :										
a) Name Elvin T. Terrell			b) Age 61							
c) Regular Job Title: Truck Driver					d) Activity at Time of Accident: Unloading pipe from truck					
<input checked="" type="checkbox"/> Contractor Employee										
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days		
a) Total:	12	7	4	b) at the mine:	1	c) at activity (23d)	12	7	4	
				d) with Contractor	3	38	2			
25. Autopsy Performed: If Yes, Location YES Tarrant County						26. Mine Telephone No.: (817) 279-1660				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was the driver of the first of four trucks to be unloaded at the mine near the primary plant. The trucks were loaded with 9 sections each of 26"OD diameter polyurethane pipe with each section 50' long and weighing approximately 1732 pounds. The pipe was stacked in three layers of three pieces each. The driver unsecured the load and the first two sections of pipe off the top layer were removed. The driver was observed walking around the truck when a section of pipe rolled off the trailer and landed on the driver.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Volvo			29. Model: D13		
30. District: M5000 South Central		32. Field Office: Dallas TX		33. Event Number: 6734017	
34. Accident Investigator: Homer Pricer			35. MSHA Person Notified: Elwood M. Burriss		Date 02/26/2016
					Time 09:04 AM
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Mac Burriss			Date 03/01/2016
38. Reason For Amendment:					