

# Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Falling, Rolling or Sliding Rock /Materl		3. Date/Time of Accident 08/03/2015 06:40 AM		4. Date/Time of Death 08/03/2015 06:40 AM		5. Fatal Case No 15		
6. Mine Information :										
a) Mining Company Name Luck Stone Corp-Leesburg			b) Mine Name Leesburg Plant			c) Parent of Mining Company Charles S Luck IV; Charles S Luck III				
7. Mine Location :		a) City Ashburn		b) County Loudoun		c) State VA		8. Mine ID Number: 44-02964	9. Union: NO	
10. Primary Mineral Mined: CRUSHED & BROKEN GRANITE MINI			11. Number of Mine Employees:		a) Total 43	b) Underground 0	c) Open Pit/Quarry 15	d) Mill/Prep Plant 21	e) Other 7	
12. Contractor Name:						13. Union		14. Contractor ID Number:		
15. Contractor Address:				a) City		b) County		c) State	d) Zip Code	
16. Number of Contractor Employees:			a) Total 3	b) Underground 0	c) Open Pit/Quarry 3	d) Mill/Prep Plant 0	e) Other 0			
17. Number of Persons in Mine at Time of Accident:						18. Number of Persons Unaccounted For:				
a) Mine Employees: 25		b) Contractor Employees: 3		a) Mine Employees: 0		b) Contractor Employees: 0				
19) Location of Accident									20. Mining Height:	
<input type="checkbox"/> 01-Underground	<input type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input checked="" type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		Feet Inches	
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility					
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1								
23. Victim Information :				a) Name Daniel Potter		b) Age 18				
c) Regular Job Title: Truck Driver (Seasonal Associate)				d) Activity at Time of Accident: Loading haul truck				<input checked="" type="checkbox"/> Mine Employee		
24. Experience :	Years Weeks Days		Years Weeks Days			Years Weeks Days			Years Weeks Days	
a) Total:	0 9 0		b) at the mine: 0 9 0			c) at activity (23d) 0 9 0			d) with Contractor 0 0 0	
25. Autopsy Performed: If Yes, Location YES Manassas, VA						26. Mine Telephone No.: (703) 729-2801				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

A haul truck driver (victim) backed his truck under a conveyor belt to be loaded. After exiting the haul truck, the victim entered a door leading underneath the "fine sand silo." When a portion of the silo failed material engulfed the victim. The victim was recovered on the next day.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:				29. Model:			
30. District: M2000 Northeastern		32. Field Office: Staunton VA				33. Event Number: 6685689	
34. Accident Investigator: Gary C. Mewine			35. MSHA Person Notified: Kevin H. Abel			Date 08/03/2015	Time 07:20 A
36. Type of Report: Initial		37. Name of Preparer and Date Prepared Joseph M. Denk				Date 08/04/2015	
38. Reason For Amendment:							