

Preliminary Report of Accident



RFP

1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 09/11/2018 04:10 PM		4. Date/Time of Death 09/11/2018 06:01 PM		5. Fatal Case No 6					
6. Mine Information :													
a) Mining Company Name Rosebud Mining Company			b) Mine Name Kocjancic			c) Parent of Mining Company J Clifford Forrest III							
7. Mine Location :													
a) City Brockway		b) County Jefferson		c) State PA		8. Mine ID Number: 36-09436		9. Union: NO					
10. Primary Mineral Mined: BITUMINOUS COAL UNDERGROUND		11. Number of Mine Employees:		a) Total 30		b) Underground 27		c) Open Pit/Quarry 0		d) Mill/Prep Plant 0		e) Other 3	
12. Contractor Name:						13. Union		14. Contractor ID Number:					
15. Contractor Address:													
a) City		b) County			c) State			d) Zip Code					
16. Number of Contractor Employees:													
a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other					
17. Number of Persons in Mine at Time of Accident:						18. Number of Persons Unaccounted For:							
a) Mine Employees: 10		b) Contractor Employees: 0		a) Mine Employees: 0		b) Contractor Employees: 0							
19) Location of Accident													
<input checked="" type="checkbox"/> 01-Underground		<input type="checkbox"/> 03-Open Pit		<input checked="" type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		20. Mining Height:			
<input type="checkbox"/> 02-Surface at Underground		<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility		Feet		Inches			
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1						3		6			
23. Victim Information :													
a) Name Kameron D. Rankin					b) Age 27								
c) Regular Job Title: Mobile Bridge Operator				d) Activity at Time of Accident: Mobile Bridge Operator				<input checked="" type="checkbox"/> Mine Employee					
24. Experience :													
Years Weeks Days			Years Weeks Days			Years Weeks Days			Years Weeks Days				
a) Total: 0 8 1			b) at the mine: 0 8 1			c) at activity (23d) 0 2 3			d) with Contractor 0 0 0				
25. Autopsy Performed: If Yes, Location YES Erie County, PA Coroner's Office						26. Mine Telephone No.: (814) 265-0192							

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
On September 11, 2018, at approximately 4:10 p.m., a Mobile Bridge Conveyor Operator was fatally injured when he was crushed between a bridge conveyor and the coal rib. At the time of the accident, the continuous mining machine was being repositioned. The bridge conveyor moved because it was connected to the mining machine.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Long-Airdox				29. Model: MBC-27C1					
30. District: C0200 New Stanton		32. Field Office: Clearfield PA				33. Event Number: 6249106			
34. Accident Investigator: Jason S. Boring				35. MSHA Person Notified: Randall Caramellino		Date 09/11/2018		Time 04:30 P	
36. Type of Report: Initial		37. Name of Preparer and Date Prepared Jason Boring				Date 09/12/2018			
38. Reason For Amendment:									