

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 06/13/2018 11:45 AM		4. Date/Time of Death 06/13/2018 11:45 AM		5. Fatal Case No 5		
6. Mine Information :										
a) Mining Company Name King Ready Mix Concrete Inc			b) Mine Name King Sand & Gravel			c) Parent of Mining Company Kay King				
7. Mine Location :		a) City Kerens		b) County Navarro		c) State TX		8. Mine ID Number: 41-04622		9. Union: NO
10. Primary Mineral Mined: CONSTRUCTION SAND & GRAVEL M			11. Number of Mine Employees:		a) Total 17	b) Underground	c) Open Pit/Quarry 17	d) Mill/Prep Plant		e) Other
12. Contractor Name:						13. Union		14. Contractor ID Number:		
15. Contractor Address:		a) City		b) County		c) State		d) Zip Code		
16. Number of Contractor Employees:		a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 14		b) Contractor Employees:			a) Mine Employees: 0		b) Contractor Employees:			
19) Location of Accident									20. Mining Height:	
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		Feet	Inches
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility					
21. Nonfatal Injuries:			22. Fatal Injuries:			1				
23. Victim Information :										
a) Name Aurelio Perez			b) Age 65							
c) Regular Job Title: Truck Driver			d) Activity at Time of Accident: Hauling pit run material			<input checked="" type="checkbox"/> Mine Employee				
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days		
a) Total:		4		b) at the mine: 4		c) at activity (23d) 4		d) with Contractor		
25. Autopsy Performed: If Yes, Location YES SW Forensic						26. Mine Telephone No.: (903) 396-2710				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
The victim was hauling material from the pit to the plant when he lost control of his truck. The truck traveled over a 40" berm into an impoundment. Divers from the local emergency service were used to retrieve the body from the cab. The top of the truck was located approximately 20 feet below the surface of the water.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Volvo			29. Model: A40 D		
30. District: M5000 South Central		32. Field Office: Dallas TX			33. Event Number:
34. Accident Investigator: David Hamm			35. MSHA Person Notified: Elwood M. Burriss		Date 06/13/2018
					Time 12:00 PM
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Elwood M Burriss			Date 06/14/2018
38. Reason For Amendment:					